

Not Askered
 L1 Rep & 2650.00
 Resurvey After Pain
 5 days



ESTIMATE TO REPAIR

VEHICLE NO. : SKN 1543.P
 MAKE : NISSAN
 MODEL : TEANA 2.0L CVT
 YEAR : 2013
 CHASSIS NO : MNTBBAL33Z0000015

SURVEYOR NAME	: Lennem LKK
DATE OF SURVEY	: 19.01.21.
TIME OF SURVEY	:

DATE : 4-Jan-21
 DATE OF ACCIDENT : 17-Nov-20
 THIRD PARTY REF : SJS 6875 J / AIG

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear bumper \$848.10	Nett		\$ 907.10	✓
1 pc	RH Rear bumper retainer	Nett		\$ 55.10	✓
10 ps	Rear bumper clips	Nett	\$ 2.60	\$ 26.00	✓
1 pc	RH Rear fender \$1,288.20	Nett		\$ 1,377.30	✓
1 pc	Rear wind screen moulding	Nett		\$ 155.90	✓
				\$ 2,521.40	
	Less 10%			\$ 252.14	\$ 2,269.26
1 tube	Rear windscreen sealant	S.Nett		\$ 40.00	✓
	To Putty & Spray Paint			\$ 500.00	4201
	To remove & refix rear windscreen glass			\$ 100.00	✓
	To Anti Rust			\$ 50.00	301
	Labour Charges			\$ 680.00	6001
				Lennem APPROVED	
TG/TL	TOTAL				\$ 3,639.26

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: