

ASS. REC. BY:

REF:

AG/2100-02161K qd3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of 06-06

Insured: _____

Policy No. 2070175444

Claims No. 8062782130SG

Sum Insured: _____ Excess: 600

(Client's Record)

Make of Veh: _____

10cm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$67k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN/OUT
Family

Veh No: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Colour: _____

Sp. Reading: _____

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. _____ mm

L/Bal. _____ mm

D.O.A. 21/12/20

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

08/01/20 @ 9.21am revert to AIG via Merimen.

15/01/21 @ 4.47pm Kok Chong informed C/A via Merimen.

15/01/21 @ 4.59pm Informed Terrence C/A & ex:\$600 by email.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

: Prell. Report

☐

: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

Tech Invs (\$ _____)

☐

Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I. (\$ _____)

TOTAL



OMEGA AUTO PTE. LTD.

160 Sin Ming Drive #06-06 Sin Ming Autocity Singapore 575722

Tel : (65) 6543 9807 Fax: (65) 6543 9805

Business Reg. No.: 200205188K GST Reg. No.: 200205188K

Date : 30 December 2020

ESTIMATE REPAIR BILL FOR TOYOTA HIACE VAN - GBK837X

PARTS

1 pc	LH sliding door
1 pc	LH sliding door outer handle
1 pc	LH sliding door inner lock
1 pc	LH sliding door inner lock catch
1 pc	LH sliding door inner trimboard
1 pc	LH sliding door weatherstrip
1 pc	LH rear body panel
1 pc	LH rear body panel inner trim board
1 pc	LH sliding door rear roller
1 pc	LH sliding door lower roller
1 pc	LH sliding door roller rail

\$	<i>Bz</i>	1,718.90	✓
\$	<i>in</i>	278.10	X
\$		578.90	✓
\$	<i>n</i>	121.30	X
\$	<i>CM</i>	368.90	✓
\$	<i>Adlha</i>	390.10	✓
\$	<i>Bz</i>	1,819.10	✓
\$	<i>in</i>	789.10	X
\$		231.90	✓
\$		278.10	✓
\$		578.10	✓
Total:		\$	7,152.50

251

S/NETT

To remove and refit rear interior fittings	\$	250.00	<i>801</i>
To transfer LH Sliding door's fittings	\$	150.00	<i>601</i>
To check wiring	\$	50.00	<i>201</i>
To dismantle refit renew the accident damaged parts. Including knock-out straighten repair reshape and adjust of the parts.	\$	1,500.00	<i>9001</i>
Rust Proofing Damaged Section	\$	<i>NZ</i> 200.00	<i>X</i>
Spray painting on replacement parts and damaged sections in and outside.	\$	1,500.00	<i>6001</i>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES

Not Authorized
LI Rep &
Recovery After Pain
Ex ??