



# OMEGA AUTO PTE. LTD

160 Sin Ming Drive #06-06 Sin Ming Autocity Singapore 575722

Tel : (65) 6543 9807 Fax: (65) 6543 9805

Business Reg. No.: 200205188K GST Reg. No.: 200205188K

Date : 30 December 2020

## **ESTIMATE REPAIR BILL FOR TOYOTA HIACE VAN - GBK837X**

### **PARTS**

1 pc	LH sliding door	\$	1,718.90
1 pc	LH sliding door outer handle	\$	278.10
1 pc	LH sliding door inner lock	\$	578.90
1 pc	LH sliding door inner lock catch	\$	121.30
1 pc	LH sliding door inner trimboard	\$	368.90
1 pc	LH sliding door weatherstrip	\$	390.10
1 pc	LH rear body panel	\$	1,819.10
1 pc	LH rear body panel inner trim board	\$	789.10
1 pc	LH sliding door rear roller	\$	231.90
1 pc	LH sliding door lower roller	\$	278.10
1 pc	LH sliding door roller rail	\$	578.10
Total:		\$	<u>7,152.50</u>

### **S/NETT**

To remove and refit rear interior fittings	\$	250.00
To transfer LH Sliding door's fittings	\$	150.00
To check wiring	\$	50.00
To dismantle refit renew the accident damaged parts. Including knock-out straighten repair reshape and adjust of the parts.	\$	1,500.00
Rust Proofing Damaged Section	\$	200.00
Spray painting on replacement parts and damaged sections in and outside.	\$	1,500.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES**

**D.**