



OMEGA AUTO PTE. LTD.

160 Sin Ming Drive #06-06 Sin Ming Autocity Singapore 575722

Tel : (65) 6543 9807 Fax: (65) 6543 9805

Business Reg. No.: 200205188K GST Reg. No.: 200205188K

Date : 30 December 2020

ESTIMATE REPAIR BILL FOR TOYOTA HIACE VAN - GBK837X

PARTS

1 pc	LH sliding door
1 pc	LH sliding door outer handle
1 pc	LH sliding door inner lock
1 pc	LH sliding door inner lock catch
1 pc	LH sliding door inner trimboard
1 pc	LH sliding door weatherstrip
1 pc	LH rear body panel
1 pc	LH rear body panel inner trim board
1 pc	LH sliding door rear roller
1 pc	LH sliding door lower roller
1 pc	LH sliding door roller rail

\$	B ₂	1,718.90	✓
\$	h	278.10	X
\$		578.90	✓
\$	n	121.30	X
\$	CM	368.90	✓
\$	putha	390.10	✓
\$	B ₂	1,819.10	✓
\$	h	789.10	X
\$		231.90	✓
\$		278.10	✓
\$		578.10	✓
Total:	\$	7,152.50	

251

S/NETT

To remove and refit rear interior fittings

\$ 250.00 801

To transfer LH Sliding door's fittings

\$ 150.00 601

To check wiring

\$ 50.00 201

To dismantle refit renew the accident damaged parts.
Including knock-out straighten repair reshape and adjust
of the parts.

\$ 1,500.00 9001

Rust Proofing Damaged Section

\$ NZ 200.00 X

Spray painting on replacement parts and damaged
sections in and outside.

\$ 1,500.00 6001

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES

LKK Auto Consultants hereby notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Scanned with CamScanner