



OMEGA AUTO PTE. LTD.

160 Sin Ming Drive #06-06 Sin Ming Autocity Singapore 575722

Tel : (65) 6543 9807 Fax: (65) 6543 9805

Business Reg. No.: 200205188K GST Reg. No.: 200205188K

Date : 30 December 2020

ESTIMATE REPAIR BILL FOR TOYOTA HIACE VAN - GBK837X

PARTS

1 pc	LH sliding door	1620-10	\$ B	1,718.90	✓
1 pc	LH sliding door outer handle		\$ In	278.10	X
1 pc	LH sliding door inner lock	269-60	\$ Del	578.90	✓
1 pc	LH sliding door inner lock catch		\$ n	121.30	X
1 pc	LH sliding door inner trimboard	356-20	\$ CM	368.90	✓
1 pc	LH sliding door weatherstrip		\$ Pulha	390.10	✓
1 pc	LH rear body panel		\$ B	1,819.10	✓
1 pc	LH rear body panel inner trim board		\$ In	789.10	X
1 pc	LH sliding door rear roller		\$ In	231.90	X
1 pc	LH sliding door lower roller		\$ n	278.10	✓
1 pc	LH sliding door roller rail		\$ In	578.10	X
258			Total:	\$	7,152.50

S/NETT

To remove and refit rear interior fittings	\$	250.00	801
To transfer LH Sliding door's fittings	\$	150.00	601
To check wiring	\$	50.00	201
To dismantle refit renew the accident damaged parts. Including knock-out straighten repair reshape and adjust of the parts.	\$	1,500.00	9001
Rust Proofing Damaged Section	\$ NZ	200.00	X
Spray painting on replacement parts and damaged sections in and outside.	\$	1,500.00	6001

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1080250