

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21000216/KQD3Q2

Date: 12/03/2021

REFERENCE

Insured/Claimant:	JOGH ENTERPRISE	Policy No:	2070175444	
Date of Loss:	21/12/2020	Nature of Claim:	OD	Claim No: 8062782130SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK837X		
Make & Model:	TOYOTA HIACE, 3.0 (A)	Engine No:	1KDB021403
Reg. Date:	18/12/2019 (Man. Year: 2019)	Chassis No:	JTFHT02P000250060
Colour:	Silver	Odometer:	93420 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$67,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	195R15X8
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,152.50	3,549.90	3,602.60	50.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	1,660.00	1,990.00	54.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,802.50	5,209.90	5,592.60	51.77
Approved Total (Overridden) (S\$)		4,150.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	10,202.50	3,550.00	6,652.50	65.20
+ GST 7.00/7.00% (S\$)	714.18	248.50	465.68	65.20
Nett Amount (S\$)	10,916.68	3,798.50	7,118.18	65.20

INSPECTION

Date of Assignment: 07/01/2021

Date Inspected: 07/01/2021 Inspected At:

Omega Auto Pte Ltd
160 Sin Ming Drive #06-06, Sin Ming
Auto City
Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH SLIDING DOOR	Bent	1,718.90 F	*1,620.10 FL
2	1		*LH SLIDING DOOR OUTER HANDLE	Serviceable	278.10 F	*- FL
3	1		*LH SLIDING DOOR INNER LOCK	Dented	578.90 F	*269.60 FL
4	1		*LH SLIDING DOOR INNER LOCK CATCH	Repair	121.30 F	*- FL
5	1		*LH SLIDING DOOR INNER TRIMBOARD	Cracked	368.90 F	*356.20 FL
6	1		*LH SLIDING DOOR WEATHERSTRIP	Dented/Cut	390.10 F	*390.10 FL
7	1		*LH REAR BODY PANEL	Bent	1,819.10 F	*1,819.10 FL
8	1		*LH REAR BODY PANEL INNER TRIM BOARD	Serviceable	789.10 F	*- FL
9	1		*LH SLIDING DOOR REAR ROLLER	Serviceable	231.90 F	*- FL
10	1		*LH SLIDING DOOR LOWER ROLLER	Distorted	278.10 F	*278.10 FL
11	1		*LH SLIDING DOOR ROLLER RAIL	Serviceable	578.10 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	7,152.50	4,733.20
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,183.30

Total Parts (\$\$)	7,152.50	3,549.90
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT REAR INTERIOR FITTINGS	New	250.00	80.00
2	TO TRANSFER LH SLIDING DOORS FITTINGS	New	150.00	60.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO DISMANTLE REFIT RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT STRAIGHTEN REPAIR RESHAPE AND ADJUST OF THE APRTS	New	1,500.00	900.00
5	RUST PROOFING DAMAGED SECTION	New	200.00	0.00
6	SPRAY PAINTING ON REPLACEMENT PARTS AND DAMAGED SECTIONS IN AND OUTSIDE	New	1,500.00	600.00
Gross Labour Cost (\$\$)			3,650.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >