

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : CHIA TI HUI SAMANTHA
257 ARCADIA ROAD
#05-02 HILLCREST ARCADIA
SINGAPORE 289851

Estimate No: MC1901661
Date: 31 Dec 2020
Policy No: MT/00563300
Veh Reg No: SJA9852A
Make/Model: VOLKSWAGEN GOLF
1.4 GT A

ATTN:

Your Ref No: SJA9852A
Claim Type: Third Party → *MC*
Accident Date: 30/12/2020
TP Veh Reg No: SMV7860T

LK 1030

Not Authorized
11 Sep @ 5050/
Recovery After Paint 4-5 days

Estimate Repair Cost to Vehicle No :SJA9852A

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 TAILGATE	1 PC	<i>B</i> 1,875.45	<i>✓</i>
2 TAILGATE EMBLEM	1 PC	<i>nn</i> 710.55	<i>✓</i>
3 TAILGATE GOLF LOGO	1 PC	<i>nn</i> 94.35	<i>✓</i>
4 TAILGATE TSI LOGO	1 PC	<i>nn</i> 87.25	<i>✓</i>
5 TAILGATE LAMP LH	1 PC	<i>CM</i> 269.70	<i>✓</i>
6 TAILGATE LOCK	1 PC	<i>R</i> 192.30	<i>✓</i>
7 TAILGATE LOCK CATCH	1 PC	<i>R</i> 98.45	<i>X</i>
8 TAILGATE INNER TRIMBOARD	1 PC	<i>in</i> 562.80	<i>X</i>
9 TAILGATE RUBBER	1 PC	<i>Adm-i</i> 323.85	<i>508in</i>
10 REAR BUMPER	1 PC	<i>Bu</i> 1,088.40	<i>✓</i>
11 REAR BUMPER LOWER GARNISH	1 PC	<i>nd</i> 400.90	<i>✓</i>
12 REAR BUMPER SIDE RETAINER LH & RH	2 PC	<i>nn</i> 93.50	<i>X</i>
13 REAR BUMPER CLIPS	12 PC	<i>nn</i> 30.00	<i>✓</i>
14 REAR BUMPER CTR RETAINER	1 PC	<i>CM</i> 112.45	<i>2</i>
15 REAR BUMPER REINFORCEMENT	1 PC	<i>R</i> 611.05	<i>✓</i>
16 REAR END PANEL	1 PC	<i>R</i> 806.85	<i>✓</i>
17 REAR END PANEL GARNISH	1 PC	<i>nd</i> 161.05	<i>✓</i>
		7,518.90	
	Less 10%	751.89	6,767.01
Special Nett			
18 INNER SEAL	1 PC	<i>nn</i> 20.00	<i>✓</i>
19 WINDSCREEN SEALANT	1 PC	<i>nn</i> 40.00	<i>✓</i>
20 NUMBER PLATE	1 PC	<i>nd</i> 35.00	<i>✓</i>
21 REVERSE SENSOR	1 SET	<i>Short</i> 200.00	<i>2</i>
		295.00	295.00
LABOUR			
22 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>2ol</i>
23 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	<i>✓</i>
24 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	60.00	<i>✓</i>
25 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	<i>3ol</i>
26 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	<i>3ol</i>



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : CHIA TI HUI SAMANTHA
257 ARCADIA ROAD
#05-02 HILLCREST ARCADIA
SINGAPORE 289851

Estimate No: MC1901661
Date: 31 Dec 2020
Policy No: MT/00563300
Veh Reg No: SJA9852A
Make/Model: VOLKSWAGEN GOLF
1.4 GT A

ATTN:

Your Ref No: SJA9852A
Claim Type: Third Party
Accident Date: 30/12/2020
TP Veh Reg No: SMV7860T

Estimate Repair Cost to Vehicle No :SJA9852A

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
27 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL.TO KNOCK & REPAIR SPARE TYRE PANEL,REAR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	500. ✓
28 TO SPRAY TAILGATE,REAR BUMPER,END PANEL.	1 PC	700.00	600. ✓
		1,840.00	1,840.00
		Total	S\$ 8,902.01
		Add GST @ 7%	623.14
		Total Amount Payable	S\$ 9,525.15

TOTAL: SINGAPORE DOLLAR NINE THOUSAND FIVE HUNDRED TWENTY FIVE AND CENTS FIFTEEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: