

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLA6824C

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR 2X AFFECTED PANEL	240.00	120 /
2 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	/ /
3 WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	X M
4 ZZ/001	TRANSFER MECHANISM PART FOR FR LH DOOR	80.00	/ /
5 ZZ/002	REPAIR FR LH FENDER, RR LH DOOR & LH SILY-OUTER RENEW FRT LH DOOR @ 350 x 2	1560.00	780 /
6 ZZ/003	S/PAINT FR/RR LH DOOR, FR LH FENDER & LH SILY-OUTER @ 250 x 2	1000.00	500 /
7 ZZ/004	CONDUCT WHEEL BALANCING FOR FR LH TYRE	15.00	X M
TOTAL LABOUR CHARGES		3088.00	1580

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLA6824C

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 SUNDRIES	NPN			40.00 20 /
2 MOUL-FR DOOR PAD,LH	80877-4CE0A	194.70	cut / /	
3 HINGE LOWR ASSY	80400-JN00A	58.90	X sul	
4 MOTOR ASSY-REG	80730-4CA0A	568.10	X sul	
5 REGULATOR-DOOR	80721-6FR0A	98.90	X sul	
6 MOULDING SASH	80283-4CA0A	106.60	ne / /	
7 TAPE-FR DOOR,LH	80819-4CA0B	19.50	ne / /	
8 DOOR-FRONT LH	H010A-4CBMA	1090.30	Lt / /	
9 CLIP-TRIM(2.7X3)	01553-10641	8.10	ne / /	
10 CLIP(3.3X2)	76882-JG10A	6.60	ne / /	
11 GROMMET(4.9X6)	76881-JG00A	29.40	ne / /	
12 CLIP(2.7X2)	76847-JG00A	5.40	ne / /	
13 GROM-PTN(2.7X4)	76848-JG00A	10.80	ne / /	
14 MOULDING ASSY-F	63861-4CE0A	180.00	8ul / /	
15 COVER ASSY-SILL	76851-4CE0A	650.00	? X sul	
SUB TOTAL		3027.30	1651.40	40.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		605.46	0.00	0.00
GRAND TOTAL		2421.84	0.00	40.00 20
OVERALL TOTAL		2461.84		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLA6824C

TOTAL LABOUR CHARGES	3088.00 1580
TOTAL SPARE PARTS CHARGES	2461.84 1341.12
GRAND TOTAL	5549.84 * 2921.12

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME

: Razul - Hg 900100618

SURVEYED DATE

: 11/01/2021 @ 1125

AUTHORIZED DATE

:

EXCESS CLAUSE

: 0.00

4 days

LIABILITY

: 0.00

REMARKS

:

Razul before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: