

# Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541  
H/p 91082728

Fax : 64816131

Nareash Kumar S/O Meenachisunram  
Blk 120D Canberra Crescent  
#12-405  
Singapore 754120

*Not Authorized*  
*11 Days @ 10,550k*  
*Perumy Aka Paim*  
*12 days*

Vehicle No : SJQ 6153 U  
Make : Kia Cerato Forte  
Year : 2009

Qty	Description	Unit Price	Amount	
<u>Estimate Cost Of Repair</u>				
2 pcs	Front headlamp assy <i>photo</i>	<i>m/c/m</i> \$497.00	\$994.00	<i>✓</i>
1 pc	Front grille		\$255.00	<i>✓</i>
1 pc	Front grille emblem	<i>photo reuse</i>	\$55.00	<i>✓</i>
1 pc	Front bumper <i>562</i>	<i>CM</i>	\$688.00	<i>✓</i>
1 pc	Front bumper reinforcement	<i>photo 351</i>	\$385.00	<i>✓</i>
1 pc	Front bumper sponge	<i>photo</i>	\$155.00	<i>✓</i>
1 pc	Front bumper lower grille		\$175.00	<i>✓</i>
1 pc	Front support panel		\$550.00	<i>✓</i>
1 pc	Rear boot lid <i>photo</i>	<i>793.80</i>	\$885.00	<i>✓</i>
1 pc	Rear boot lid inner lock		\$155.00	<i>✓</i>
1 pc	Rear boot lid outer chrome handle		\$197.00	<i>✓</i>
1 pc	Rear boot lid emblem "KIA"	<i>way</i>	\$48.00	<i>✓</i>
1 pc	Rear boot lid emblem "Cerato"	<i>me</i>	\$45.00	<i>✓</i>
2 pcs	Rear boot lid lamp <i>photo @ 405</i>	<i>MS TW</i>	\$655.00	<i>✓</i>
2 pcs	Rear tail-lamp panel <i>@ 605</i>	<i>ols cm</i>	\$775.00	<i>✓</i>
1 pc	Rear boot rubber	<i>m/c/m/ra</i>	\$235.00	<i>✓</i>
1 pc	Rear end panel	<i>93-506w</i>	\$270.00	<i>470</i>
1 pc	Rear end panel inner garnish	<i>cm</i>	\$187.00	<i>506w</i>
1 pc	Rear fender inner trim board	<i>cm</i>	\$488.00	<i>✓</i>
1 pc	Rear n/s fender air duct	<i>dit</i>	\$155.00	<i>✓</i>
1 pc	Rear fender innershield		\$305.00	<i>✓</i>
1 pc	Rear spare tyre panel		\$125.00	<i>✓</i>
1 pc	Rear spare tyre cover board		\$85.00	<i>✓</i>
1 pc	Rear bumper <i>658</i>	<i>RA/AN</i>	\$170.00	<i>✓</i>
1 pc	Rear bumper bracket		\$685.00	<i>✓</i>
1 pc	Rear bumper side retainer		\$278.00	<i>✓</i>
1 pc	Rear bumper reinforcement <i>356</i>	<i>RA</i>	\$685.00	<i>✓</i>
1 pc	Rear bumper sponge		\$85.00	<i>✓</i>
			\$75.00	<i>✓</i>
			\$110.00	<i>✓</i>
			\$385.00	<i>✓</i>
			\$135.00	<i>✓</i>
			balance c/f	\$11,905.00
	Bonnet <i>✓ 615.70 RA ✓</i>			
	Boot lid insulator <i>✓ 195.10 Refam ✓</i>			

Faster  
memoryPrecision  
touchpadFast  
wirelessSJQ 6153 U

3  
 1 pcs Rear reverse sensor e 210  
 1 pc Rear exhaust silencer 762.

balance b/f \$11,905.00 630  
 CMA/Shop \$265.00 \$1,060.00 LTT  
 RM \$885.00 7  
 \$13,850.00  
 Less 10 % \$1,385.00  
 \$12,465.00

S. Nett Item

1 pc Front no plate  
 1 pc Rear spare tyre panel black insulator  
 1 pc Rear no plate  
 20 pcs Rear bumper clip

ND \$40.00 ✓  
 NM \$200.00 10012  
 ND \$40.00 ✓  
 NM \$40.00 ✓  
 \$2.00  
 \$790.00

Labour Charges

Remove/renew the above parts including knocking, cutting & welding. \$1,600.00 1400  
 To putty & spray paint on accident affected portion. \$1,600.00 1400  
 Check/reconnect wiring. \$45.00 40  
 To spray anti rust on accident affected portion. \$200.00 120  
 Remove/refit rear boot upholstery to facilitate repair. \$120.00 80  
 Remove/refit fuel tank to facilitate repair. \$100.00 60  
 Remove/renew rear exhaust silencer \$150.00 60  
 Remove/refit air con condenser and to top up gas \$180.00 100  
 Total \$17,250.00

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: