



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|---|-----------------|--|--|
| AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN | | | Ref: CC4/ASM21000227/Uba3q2 Date: 13/07/2021 Code: ASM | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SHD 6920P | Veh. Inspected | SLZ 9041T | |
| Policy No. | VFX/P2419138 | Coverage (\$) | 0.00 | |
| Claim No. | S1M034MQ | Excess (\$) | 0.00 | |
| Assign From | | Assign Date | 06/01/2021 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HONDA SHUTTLE (A) | c.c | 1496 | |
| Engine No. | HIDDEN | Year of Reg. | 2018 | |
| Chassis No. | GK81202097 | Colour | BLACK | |
| Odometer | 42967 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | FAIR | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 185/60 R15 | MICHELIN | 8 mm | |
| L/H Front Tyre | 185/60 R15 | MICHELIN | 8 mm | |
| R/H Rear Tyre | 185/60 R15 | MICHELIN | 8 mm | |
| L/H Rear Tyre | 185/60 R15 | MICHELIN | 8 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.THE UNDERCARRIAGE AND CHASSIS FRAME AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 03/01/2021 | Inspection Date | 06/01/2021 | |
| Survey held at | FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 13 Working Days | |