#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI21000229/R1TD3E2

**Date:** 08/07/2021

**REFERENCE** 

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No: DMCG20003794

Claimant Vehicle GBG3094Z Insured Vehicle No: YP2098A

Date of Loss: 04/01/2020 Nature of Claim: TP Claim No: CDMCG21000021

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: GBG3094Z

 Make & Model:
 NISSAN NV200, 1.6 DX-2 (A)
 Engine No:
 HR16088382D

 Reg. Date:
 18/07/2017 (Man. Year: 2016)
 Chassis No:
 VM20105410

 Colour:
 Black
 Odometer:
 82367 km

Engine Capacity: 1597 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70R14 Rear Tyre Size: 185/70R14
Front Left Side: Greenways 6 mm Rear Left Side: Greenways 6 mm
Front Right Side: Greenways 6 mm
Greenways 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,467.00	1,270.50	196.50	13.39
Miscellaneous Items		0.00	0.00	0.00	
Labour		342.00	328.50	13.50	3.95
Paintwork Labour		258.53	321.72	-63.19	-24.44
Towing		0.00	0.00	0.00	
Calculated Gross To	otal (S\$)	2,067.53	1,920.72	146.81	7.10
Approved Total (Overridd	len) (S\$)		1,500.00		
	(S\$)	2,067.53	1,500.00	567.53	27.45
+ GST 7.00/7.0	00% (S\$)	144.73	105.00	39.73	27.45
Nett Amo	ount (S\$)	2,212.26	1,605.00	607.26	27.45

**INSPECTION** 

Date of Assignment: 06/01/2021 Present Location: Mova Automotive Pte Ltd (Bukit Merah)

Mova Automotive Pte Ltd (Bukit Merah)

Date Inspected: 06/01/2021 Inspected At: Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3

Singapore 159722

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL Manager: DENISE TAY KWEE CHENG

# **REPAIR DETAILS**

### Reference

Part Source: (Last Synchronised: 08 Jul 2021)

Parts: N/A NISSAN NV200 1.6 DX-2 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBG3094Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*FRONT BUMPER (WCP)	Cut	330.00 F	*330.00 F
2	1	NA	*L/DOOR MIRROR ASSY (WCP)	Cracked	300.00 F	*300.00 F
3	1	NA	*L/F BUMPER BRACKET (WCP)	Serviceable	25.00 F	*-F
4	1	NA	*L/F DOOR FRONT STRIP (WCP)	Serviceable	100.00 F	*-F
5	1	NA	*L/F WING (WCP)	Bent	300.00 F	*300.00 F
6	1	NA	*L/LWR QTR PANEL MLDG (WCP)	Deformed	65.00 F	*65.00 F
7	1	NA	*SUNDRY PARTS (NPA)	Not Necessary	0.00 F	*-FS
8	1	NA	*AUDATEX FEE SN	Necessary	40.00 FS	*40.00 FS
9	1	NA	*STICKER-COM. ADDRESS SN	Necessary	15.00 FS	*10.00 FS
10	1	NA	*TYRE SN (70%)	Cut	180.00 FS	*126.00 FS
F=Fra	nchise	part. S=SpcNe	tt.	_		
				Sub Total (S\$)	1,355.00	1,171.00
			+ Margin o	n L,N Items 10.00/10.00% (S\$)	112.00	99.50
				Total Parts (S\$)	1,467.00	1,270.50

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Pair</u>	ntwork Labour			
1	Total Paint Labour	New	198.00	238.50
2	Total Paint Materials	New	60.53	83.22
Lab	our Items			
3	Total Panel/Mechanical Labour	New	342.00	328.50
		Gross Labour Cost (S\$)	600.53	650.22
	Report	was unsubmitted during this print-out.		

< END OF ESTIMATES >