

GR
PRS

CTI
ASSIGNMENT

64911R

18 Apr 2005
(2005)

Unrated Cost

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Inspect Vehicle No

Workshop m/s 1st Autopro

Insured

Policy No DMCVSNA00029462000

Claim No SNM21D200054C02

Insured Excess

(Client's Record)

Make of Veh

(Policy Condition)

Remark The veh had commenced its repair at the time of inspection.

Est or Market Value

\$28K

DAC Accident Report

Consistent? Yes or No

Est / PR Seen

Consistent? Yes or No

Est Repairs

10

days

Rep

Yes or No

Est Sum

%

3 Val

Yes or No

SA / REV / REP. / 24 HRS

Date

Person Contacted

Vehicle IN / OUT

Motor Car / M Cycle / Bus / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make

Toyota Hilux

Colour

Silver

Chassis No

383389

Engine

CVR

Gen Cond ☒ Good / Fair / Poor / Burnt

Steering ☒ Inter / Jammed / Leaked / Burnt or

Brake ☒ Inter / Jammed / Leaked / Burnt or

Mod ☒ S/Rim / STD A/Rim or

Tyre Size

F: 195 R15

R

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal

8

mm

L/Bal

5

mm

D.O.A

Rear

R/Bal

5

mm

L/Bal

5

mm

D.O.L

06-01-21

Survey held at

w/s

Des of Damages ☒ Frt ☒ Rear ☒ DIS ☒ NIS / UIC / Rooftop or

5:15pm

The ☒ Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

COE: 10389

\$8000 - \$10K

Submit PRS.

Date/Time File Pass to

☐

Prel. Report

19/01 Typist

☐

Final Report

Date/Time File Return to

Days Of Repair: 10

Resurvey No. of Trip:

Adcl Fee:

☐

Site Insp: (\$

☐

Interview: (\$

☐

Photo: (\$

☐

Other: (\$

Survey Fee:

Transportation

Site Insp: (\$

Interview: (\$

Photo: (\$

Other: (\$

MER-PRS