



S THREE AUTOMOTIVE RECOVERY PTE LTD

TO :
ATTN : MOTOR CLAIM DEPT.

T/P VEH. NO. : SKK9229K & SKN9867C

ESTIMATE REPORT 1st QUOTATION

OWNER'S PARTICULAR

NAME : SILBERT TAN SI YONG
ADDRESS :

JOB NO. :

CONTACT :

LICENSE NO SJM9203K TRANS. :
MAKE / MODEL : HONDA FIT
OWNER'S INSURER NTUC INCOME
JOB-CODE : TP S/A : JOEY

CHASSIS NO :
ENGINE NO :

ACCIDENT DATE : 05-Jan-20

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR. DISP	REV. PRICE
1 FRONT BUMPER	568.70 1.00	632.50	20.00	506.00	Y	one ✓
2 FRONT BUMPER SIDE RETAINER LH	1.00	56.00	20.00	44.80	Y	one ✓
3 FRONT BUMPER SIDE RETAINER RH	1.00	56.00	20.00	44.80	Y	one ✓
4 FRONT BUMPER REINFORCEMENT	1.00	144.52	20.00	115.62	Y	? bt ✓
5 FRONT BUMPER LOWER GRILLE CENTRE	1.00	116.92	20.00	93.54	Y	? de ✓
6 FRONT BUMPER LOWER SPOILER	1.00	680.00	20.00	544.00	Y	Rx one X under SN
7 FRONT BUMPER SIDE GRILLE LH	1.00	10.52	20.00	8.42	Y	? X ny ✓
8 FRONT BUMPER SIDE GRILLE RH	1.00	10.52	20.00	8.42	Y	? X ny ✓
9 WIPER TANK ASSY	1.00	208.00	20.00	166.40	Y	X de ✓
10 FRONT GRILLE	1.00	116.92	20.00	93.54	Y	one ✓
11 FRONT GRILLE LOGO	1.00	23.42	20.00	18.74	Y	one ✓
12 FRONT BONNET	580 1.00	1800.00	20.00	1440.00	Y	bt ✓
13 FRONT BONNET GRILLE	1.00	160.00	20.00	128.00	Y	X ny ✓
14 FRONT BONNET HINGE LH	1.00	28.92	20.00	23.14	Y	Rx ✓
15 FRONT BONNET HINGE RH	1.00	28.92	20.00	23.14	Y	Rx ✓
16 FRONT BONNET LOCK	1.00	35.02	20.00	28.02	Y	Rx ✓
17 FRONT HEADLAMP LH	570.70 1.00	744.60	20.00	595.68	Y	one ✓
18 FRONT HEADLAMP RH	570.70 1.00	744.60	20.00	595.68	Y	one ✓
19 FRONT HEADLAMP LOWER BRACKET LH	1.00	25.03	20.00	20.02	Y	? one ✓
20 FRONT HEADLAMP LOWER BRACKET RH	1.00	25.03	20.00	20.02	Y	? one ✓
21 FRONT WASHER TANK	1.00	158.42	20.00	126.74	Y	X ny ✓
22 FRONT FENDER LH	1.00	375.62	20.00	300.50	Y	Rx ✓
23 FRONT FENDER RH	1.00	375.62	20.00	300.50	Y	Rx ✓
24 FRONT FENDER INNER SHIELD LH	1.00	78.12	20.00	62.50	Y	X de ✓
25 FRONT FENDER INNER SHIELD RH	1.00	78.12	20.00	62.50	Y	X de ✓
26 FRONT SUPPORT PANEL ASSY	1.00	360.32	20.00	288.26	Y	Rx bt ✓

27	RADIATOR FAN COWLING	1.00	89.80	20.00	71.84	Y	X	} un
28	RADIATOR FAN MOTOR	1.00	282.82	20.00	226.26	Y	X	
29	RADIATOR FAN BLADE	1.00	53.82	20.00	43.06	Y	X	
30	RADIATOR TOP HOSE	1.00	37.21	20.00	29.77	Y	X	
31	RADIATOR BOTTOM HOSE	1.00	21.00	20.00	16.80	Y	X	
32	RADIATOR SPARE TANK	1.00	42.12	20.00	33.70	Y	X	
33	RADIATOR BY PASS PIPE	1.00	0.00	20.00	0.00	Y	X	} un
34	AIR CON CONDENSOR	1.00	553.62	20.00	442.90	Y	? bt	
35	AIR CON FAN COWLING	1.00	81.82	20.00	65.46	Y	X	
36	AIR CON FAN MOTOR	1.00	266.51	20.00	213.21	Y	X	
37	AIR CON FAN BLADE	1.00	53.82	20.00	43.06	Y	X	
38	AIR CLEANER BOX HOSE	1.00	61.82	20.00	49.46	Y	X	
39	REAR BUMPER	497 1.00	665.80	20.00	532.64	Y	de	
40	REAR BUMPER BRACKET LH	1.00	215.60	20.00	172.48	Y	net	
41	REAR BUMPER BRACKET RH	1.00	215.60	20.00	172.48	Y	net	
42	REAR BUMPER SIDE RETAINER LH	1.00	115.60	20.00	92.48	Y	net	
43	REAR BUMPER SIDE RETAINER RH	1.00	115.60	20.00	92.48	Y	net	
44	REAR TAILGATE	771.85 1.00	986.20	20.00	788.96	Y	bt	
45	REAR TAILGATE WEATHERSTRIP	138 1.00	362.20	20.00	289.76	Y	? twi	
46	REAR TAILGATE LOCK	189 1.00	290.20	20.00	232.16	Y	? bt	
47	REAR TAILGATE LOCK CATCH	110.40 1.00	195.60	20.00	156.48	Y	? bt	
48	REAR TAILGATE GARNISH	1.00	220.00	20.00	176.00	Y	X un	
49	REAR TAILGATE INNER TRIMBOARD	252.49 1.00	355.60	20.00	284.48	Y	? de	
50	REAR TAILGATE LOGO	1.00	78.30	20.00	62.64	Y	net	
51	REAR TAILGATE DAMPER LH	1.00	138.00	20.00	110.40	Y	X	} un
52	REAR TAILGATE DAMPER RH	1.00	138.00	20.00	110.40	Y	X	
53	REAR TAILGATE HINGE LH	1.00	128.00	20.00	102.40	Y	Rp	
54	REAR TAILGATE HINGE RH	1.00	128.00	20.00	102.40	Y	Rp	
55	REAR TAILGATE TOP MOULDING	1.00	346.80	20.00	277.44	Y	net	
56	REAR TAILGATE 3RD BRAKE ASSY	1.00	358.00	20.00	286.40	Y	X un	
57	REAR END PANEL	476 1.00	578.00	20.00	462.40	Y	? bt	
58	REAR END PANEL GARNISH	155 1.00	228.20	20.00	182.56	Y	? de	
59	REAR TAILLAMP RH	442.10 1.00	992.40	20.00	793.92	Y	? au	
60	REAR TAILLAMP LH	442.10 1.00	992.40	20.00	793.92	Y	au	
61	REAR TAILLAMP LOWER PANEL LH	1.00	627.00	20.00	501.60	Y	Rp	
62	REAR TAILLAMP LOWER PANEL RH	1.00	627.00	20.00	501.60	Y	Rp	

63	REAR FENDER INNER GARNISH	1.00	957.20	20.00	765.76	Y	X NN
64	REAR FENDER RH	1.00	1280.00	20.00	1024.00	Y	Rp
65	REAR FENDER INNER SHIELD RH	1.00	230.00	20.00	184.00	Y	? xnn
66	REAR FENDER 1/4 GLASS MOULDING	1.00	165.00	20.00	132.00	Y	X
67	REAR FENDER AIR VENT	1.00	145.00	20.00	116.00	Y	X? XNN
68	REAR WINDSCREEN MOULDING	1.00	158.20	20.00	126.56	Y	net
69	REAR EXHAUST PIPE	1.00	780.00	20.00	624.00	Y	? XNN
70	REAR EXHAUST PIPE MOUNTING	1.00	190.00	20.00	152.00	Y	? xnn
71	REAR EXHAUST PIPE CENTRE	1.00	1120.00	20.00	896.00	Y	X
72	REAR AXLE PIPE CENTRE MOUNTING	1.00	94.00	20.00	75.20	Y	X
73	REAR WHEEL BEARING RH	1.00	480.00	20.00	384.00	Y	X
74	REAR WHEEL HUP BEARING LH	1.00	255.30	20.00	204.24	Y	X
75	REAR WHEEL HUP BEARING RH	1.00	255.30	20.00	204.24	Y	X
76	REAR TYRE RH	1.00	1680.00	20.00	1344.00	Y	X
77	SPARE TYRE BOARD	1.00	432.50	20.00	346.00	Y	? xnn
78	SPARE TYRE PANEL	1.00	998.10	20.00	798.48	Y	Rp

TOTAL PARTS

26936.72

21549.38

8850.91.

20% - 7080.73

SPECIAL NET ITEMS

1	FRONT BUMPER CLIPS	1.00	50.00	0.00	50.00	Y	30.
2	FRONT BUMPER LOWER SPOILER	1.00	680.00	0.00	680.00	Y	Xander 480.
3	FRONT BUMPER LOWER SPOILER SEALANT	1.00	80.00	0.00	80.00	Y	X nn
4	REVERSE CAMERA	1.00	380.00	0.00	380.00	Y	X nn
5	REAR FENDER INNER SHIELD CLIPS	1.00	50.00	0.00	50.00	Y	20? ✓ NEC
6	REAR BUMPER SPOILER	1.00	680.00	0.00	680.00	Y	480 de ✓
7	REAR BUMPER SPOILER SEALANT	1.00	80.00	0.00	80.00	Y	480 net ✓
8	REAR WINDSCREEN SEALANT	1.00	50.00	0.00	50.00	Y	net ✓
9	REAR WINDSCREEN INNER SEAL	1.00	50.00	0.00	50.00	Y	net ✓
10	REAR WINDSCREEN CLEANER & PRIMER	1.00	50.00	0.00	50.00	Y	net ✓
11	REAR BUMPER CLIPS	1.00	50.00	0.00	50.00	Y	30 net ✓
12	REAR NO. PLATE	1.00	50.00	0.00	50.00	Y	45 bl ✓
13	REVERSE SENSOR 1 SET	1.00	280.00	0.00	280.00	Y	200 nn ✓
14	REAR 1/4 GLASS SEALANT	1.00	50.00	0.00	50.00	Y	? X ?
15	REAR 1/4 GLASS INNER SEAL	1.00	50.00	0.00	50.00	Y	? X ?
16	REAR 1/4 GLASS CLEANER & PRIMER	1.00	50.00	0.00	50.00	Y	? X ?

TOTAL PARTS

2680.00

2680.00

1475

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA FRONT	1.00	1500.00	0.00	1500.00	Y	1200.500
2	STRAIGHTEN & PANEL BEAT ACCIDENT AREA -REAR	1.00	1500.00	0.00	1500.00	Y	900

3	SPRAY PAINTING ON AFFECTED AREA - FRONT	1.00	1500.00	0.00	1500.00	Y	<u>800</u> 900
4	SPRAY PAINTING ON AFFECTED AREA - REAR	1.00	1500.00	0.00	1500.00	Y	<u>1000</u> 1200.
5	CHECK & REPAIR WIRING SYSTEM	1.00	120.00	0.00	120.00	Y	<u>30</u>
6	R&R TAILGATE COMPONENTS	1.00	120.00	0.00	120.00	Y	<u>60</u>
7	R&R SPARE TYRE BOARD, CARPET & TRIM	1.00	120.00	0.00	120.00	Y	<u>60</u>
8	REPRAY TUFF KOTE ON AFFECTED AREA	1.00	120.00	0.00	120.00	Y	<u>60</u>
9	R&R REVERSE SENSOR SYSTEM	1.00	120.00	0.00	120.00	Y	<u>30</u>
10	R&R EXHAUST SYSTEM	1.00	180.00	0.00	180.00	Y	<u>80?</u> photo x
11	R&R REAR WINDSCREEN GLASS	1.00	150.00	0.00	150.00	Y	<u>120</u>
12	R&R REAR SUSPENSION SYSTEM	1.00	280.00	0.00	280.00	Y	<u>X</u>
13	R&R 1/4 GLASS GLASS	1.00	120.00	0.00	120.00	Y	<u>280</u> x
14	R&R REAR SEATS & INNER TRIM TO ASSIT REPAIR	1.00	180.00	0.00	180.00	Y	<u>80?</u> photo x
15	R&R REVERSE CAMERA & CALIBRATION	1.00	180.00	0.00	180.00	Y	<u>30</u> 3890
LABOUR			7690.00		7690.00		

EXCESS: : \$\$

NO. OF DAY :

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : \$\$

DATE OF SURVEY : / /

SURVEY BY :

CONTACT N°:

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

offia: 67418434
 Taufik 97495749
 'wp'
 10 days 12 days
 4/5 Repair after repair. 7/1/21 e 1045.

7080.73

1475

3890

12445.73.

20% - 995658

Repair limit \$ 8000

∴ COR 454 8000

12 days