



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS3/AGI20011526/R1vd3e2-1 Date: 13/01/2021 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SCL 24H	Veh. Inspected	SMP 9149H
Policy No.		Coverage (\$)	0.00
Claim No.	C10007680	Excess (\$)	0.00
Assign From	JUSTIN WONG	Assign Date	04/01/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA SHUTTLE HYBRID 1.5 A	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GP72003480	Colour	BLUE
Odometer	29897 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm
L/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/10/2020	Inspection Date	23/10/2020
Survey held at	WILLIAM LEE CAR AIR CON ENGINEERING No.1 SOON LEE STREET #06-04 PIONEER CENTRE SINGAPORE 627605		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	