



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle No: YN8114H
Appraisal Schedule

Report No: AAS/2020/202

S/N	Parts Description	Qty	Condition		Repairer's Est	Revised Est
1	Rear wooden gate with hinges	1	Dented/Cracked	X SVC	\$ 1,200.00	\$ 1,200.00
2	Sticker '60km/h'	1	Necessary	/	\$ 15.00	\$ 15.00
3	Sticker '21pax'	1	Necessary	/	\$ 15.00	\$ 15.00
4	Rear deck horizontal plank	1	Cracked	X	\$ 150.00	\$ 150.00
5	Rear deck vertical plank LH/RH	2	Cracked	X SVC 950.00	\$ 1,900.00	\$ 1,900.00
6	Rear deck step plank	1	Cracked	X	\$ 100.00	\$ 100.00
7	Tail lamp RH	1	Cracked	/	\$ 85.00	\$ 85.00

Special nett total: \$ 3,465.00 \$ 3,465.00 115

S/N	Labour Description	Repairer's Est	Revised Est
1	To lift up wooden deck, replace damaged wooden planks and parts, realign rear deck.	\$ 1,800.00	\$ 1,000.00 200 500
2	Check lightings & wirings.	\$ 50.00	\$ 30.00 /
Labour Total:		\$ 1,850.00	\$ 1,030.00

Grand Total: \$ 5,315.00 \$ 4,495.00

The final adjusted lump sum amount is \$3,600.00

Under normal circumstances, the repair should be completed within a reasonable period of 4 working days.

4- Photographs were taken at the time of inspection.

645 405
20% = 350
500
1 Day

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.