

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III21000266/UBA3Q2
Date: 11/05/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SKA3791U	Insured Vehicle No :	SHC2193C
Date of Loss:	30/12/2020	Nature of Claim:	TP
		Claim No:	MCT20120563

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA3791U	Engine No:	CAX751999
Make & Model:	VOLKSWAGEN NEW GOLF, 1.4 TSI (A)	Chassis No:	WVWZZZ1KZBW160691
Reg. Date:	24/02/2011 (Man. Year: 2010)	Odometer:	170741 km
Colour:	Silver		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/40Z R18	Rear Tyre Size:	235/40Z R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,478.43	1,948.50	4,529.93	69.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	1,820.00	1,030.00	36.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,328.43	3,768.50	5,559.93	59.60
Approved Total (Overridden) (S\$)		2,500.00		

(S\$)	9,328.43	2,500.00	6,828.43	73.20
+ GST 7.00/7.00% (S\$)	652.99	175.00	477.99	73.20
Nett Amount (S\$)	9,981.42	2,675.00	7,306.42	73.20
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 06/01/2021

Date Inspected: 06/01/2021

Estimated Period of Repair: 5.0 days

Inspected At: Precise Auto Service (HQ)
No 1 Kaki Bukit Ave 6, #02-34/36
Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2021)
Parts:	144	VOLKSWAGEN NEW GOLF 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA3791U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Badly Dented	1,835.00 FL	*1,615.00 FL
2	1		*FRONT DOOR WEATHERSTRIPE	Not Necessary	255.00 FL	*- FL
3	1		*FRONT DOOR STOPPER	Not Necessary	5.00 FL	*- FL
4	2		*FRONT DOOR HINGE	Not Necessary	404.00 FL	*- FL
5	1		*FRONT DOOR CHECKER	Not Necessary	120.00 FL	*- FL
6	1		*REAR DOOR RH	Repair	1,700.95 FL	*- FL
7	1		*REAR DOOR WEATHERSTRIPE	Not Necessary	255.00 FL	*- FL
8	1		*FRONT DOOR STOPPER	Not Necessary	5.00 FL	*- FL
9	2		*FRONT DOOR HINGE	Not Necessary	404.00 FL	*- FL
10	1		*REAR DOOR CHECKER	Not Necessary	120.00 FL	*- FL
11	1		*FRONT FENDER RH	Repair	488.75 FL	*- FL
12	1		*ROCKER PANEL RH	Dented / Bent	550.00 FL	*550.00 FL
13	1		*SPORT RIM ASSY RH	Repair	950.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,092.70	2,165.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	614.27	216.50
Total Parts (\$\$)	6,478.43	1,948.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIX FRONT & REAR RH DOOR MECHANISM	New	380.00	60.00
2	TO ADJUST COMPUTER WHEEL ALIGNMENT	New	120.00	60.00
3	TO RESPRAY AFFECTED AREAS	New	1,250.00	1,000.00
4	TO REMOVE & REFIX FRONT & REAR RH SPORT RIM & CONTACT WHEEL BALANCING	New	200.00	0.00
5	TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR AND ALIGNED ALL PARTS	New	900.00	700.00
Gross Labour Cost (S\$)			2,850.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >