

Section A - Accident Details

Registration Number	SHF3R
Case Reference Number	TAX/12/20/2076
Registration Date	3/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	YONG TECK FONG
Type of Accident	Head To Side
Accident Date and Time	30/12/2020 7:40 PM
Accident Reported Date and Time	31/12/2020 9:45 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24109296
Special Instruction to ARC, if any	FRONT LEFT PORTION
Prepared Date and Time	31/12/2020 4:14 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,352.00	\$1,000.00
Total Spray Cost	\$4,788.00	\$1,480.00
Total Spare Part Cost	\$50,377.01	\$22,418.83
Total Other Cost	\$2,786.00	(\$3,998.83)
TOTAL COST	\$59,303.01	\$20,900.00 (L/S)
Lump Sum Total	\$59,300.00	\$0.00
Number of Repair Days	12.0	11.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	11/01/2021 6:44 PM	11/01/2021 4:49 PM
Signature		
Remarks	Total number of repair days = 11 days. SUP = + 4 days.	L/S, after paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2102-0065	Invoice Number	
Quotation Date	05.02.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$1,352.00	\$1,000.00
Total Labour	\$1,352.00	\$1,000.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY APRON PANEL RH	\$180.00	\$100.00 / Supp
TO RESPRAY FRONT CHASSIS FRAME LH	\$180.00	\$100.00 / Supp
TO RESPRAY FRONT CHASSIS FRAME RH	\$180.00	\$100.00 / Supp
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 /
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00 /
TO REPSRAY FRONT HOOD	\$378.00	\$200.00 /
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$100.00 /
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00 /
TO RESPRAY APRON PANEL RH	\$180.00	\$0.00 /
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00 /
TO RESPRAY APRON PANEL LH	\$180.00	\$80.00 /
TO RESPRAY RIM	\$360.00	\$0.00 /
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00 /
TO REPRAY FRONT PILLAR RH	\$180.00	\$0.00 /
TO RESPRAY FRONT PILLAR LH	\$180.00	\$0.00 /
RESPRAY MIRROR COVER LH	\$180.00	\$0.00 /
RESPRAY MIRROR COVER RH	\$180.00	\$0.00 /
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00 /
TO RESPRAY REAR BUMPER	\$378.00	\$0.00 /
Total Spray Painting & Panel Beating	\$4,788.00	\$1,480.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$5,208.83)
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00 /
TO REMOVE AND REFIX VIEW MIRROR	\$120.00	\$0.00 /
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00 /
TO REMOVE / REFIT WINDSCREEN	\$250.00	\$100.00 /
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$450.00	\$450.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00 /
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00 /
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 /

TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$56.00	\$0.00
TO REMOVE AND REFIT ENGINE WIRE ROOM	\$200.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$80.00	\$0.00
TO REMOVE AND REFIT ENGINE MOUNTING	\$250.00	\$150.00
TO ALIGN FRONT CHASSIS FRAME LH	\$400.00	\$200.00
TO ALIGN FRONT CHASSIS FRAME RH	\$400.00	\$200.00
Total Other Costs	\$2,786.00	(\$3,998.83)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52119479 62	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace	CRU
		52115470 50	SUPPORT, FR BUMPER RH	1.00	\$76.90	25.00	\$57.68	Replace	Replace	BR
		52116470 50	SUPPORT, FR BUMPER LH	1.00	\$82.30	25.00	\$61.73	Replace	Replace	BR
		52127479 07	COVER, FR BUMPER RH	1.00	\$28.10	25.00	\$21.08	Replace	Replace	MIS
		52128479 06	COVER, FR BUMPER LH	1.00	\$28.10	25.00	\$21.08	Replace	Replace	MIS
		52114471 90	BRACKET, FR BUMPER	1.00	\$99.80	25.00	\$74.85	Replace	Replace	CRA
			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace	MIS
			NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace	MIS
		52021471 10	REINFORCEMENT FRONT UPPER	1.00	\$691.10	25.00	\$518.33	Replace	Replace	BT
		52611471 40	ABSORBER, FR BUMPER	1.00	\$70.30	25.00	\$52.73	Replace	Replace	CRU
		52103470 10	EXTENSION SUB-ASSY, LH	1.00	\$116.30	25.00	\$87.23	Replace	Replace	BT
		52102470 20	EXTENSION SUB-ASSY, RH	1.00	\$116.30	25.00	\$87.23	Replace	Replace	BT
		52132470 10	REINFORCEMENT FRONT LOWER	1.00	\$238.50	25.00	\$178.88	Replace	Replace	BT
		52618470 90	ABSORBER, FR BUMPER LOWER	1.00	\$117.00	25.00	\$87.75	Replace	Replace	CRU
		53395470 40	SEAL, HOOD TO FR END	1.00	\$24.40	25.00	\$18.30	Replace	Replace	CRU
		53289470 72	COVER, RADIATOR	1.00	\$227.80	25.00	\$170.85	Replace	Replace	CRU
		75310470 60	EMBLEM ASSY FRONT	1.00	\$87.10	25.00	\$65.33	Replace	Replace	MIS
		53112472 40	GRILLE, RADIATOR	1.00	\$165.00	25.00	\$123.75	Replace	Replace	CRU
		53101470 80	GRILLE SUB-ASSY	1.00	\$335.60	25.00	\$251.70	Replace	Replace	CRU
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	Nec
		51420470 30	COVER ASSY, ENGINE	1.00	\$180.10	25.00	\$135.08	Replace	Replace	CRU
		51410470 20	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$452.80	0.00	\$0.00	Replace	Check	X Svc
		51447470 30	COVER, ENGINE UNDER CENTER	0.00	\$94.50	0.00	\$0.00	Replace	Check	X Svc
		51443470 20	COVER, ENGINE UNDER SIDE RH	0.00	\$76.90	0.00	\$0.00	Replace	Check	X Svc
		51444470 10	COVER, ENGINE UNDER SIDE LH	1.00	\$76.90	25.00	\$57.68	Replace	Replace	MIS
		51442470 30	COVER, ENGINE UNDER, REAR	0.00	\$36.50	0.00	\$0.00	Replace	Check	X Svc
		561014E9 59	WINDSCREEN FRONT GLASS SUB-ASSY	1.00	\$1,626.40	25.00	\$1,219.80	Replace	Replace	BR
			SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace	Nec
		75535470 20	MOULDING RH	0.00	\$83.30	0.00	\$0.00	Replace	Check	X Svc
		75536470 20	MOULDING LH	0.00	\$83.30	0.00	\$0.00	Replace	Check	X Svc
		55708472 30	WIPER GARNISH LOUVER SUB-ASSY	0.00	\$666.90	0.00	\$0.00	Replace	Check	X Svc
		55753470 90	WIPER GARNISH SHIELD, COWL WATER, RH	0.00	\$18.90	0.00	\$0.00	Replace	Check	X Svc
		55754470 70	WIPER GARNISH SHIELD, COWL WATER, LH	0.00	\$18.90	0.00	\$0.00	Replace	Check	X Svc

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number: 63685592
Estimator Telephone Number: 68662623
Accident Reporting Number: 68662672

Date Generated : 05/02/2021

User ID : PohSuan

16562370	10	SEAL, RADIATOR TO RH	0.00	\$24.80	0.00	\$0.00	Replace	Check	X	SVC
16563370	10	SEAL, RADIATOR TO LH	0.00	\$24.80	0.00	\$0.00	Replace	Check	X	SVC
16593370	40	GUIDE, RADIATOR AIR , RH	0.00	\$54.60	0.00	\$0.00	Replace	Check	X	SVC
16595370	50	GUIDE, RADIATOR AIR , LH	0.00	\$58.80	0.00	\$0.00	Replace	Check	X	SVC
16400373	10	RADIATOR ASSY	1.00	\$1,841.10	25.00	\$1,380.83	Replace	Replace	X	CRU
16361370	70	FAN RADIATOR , RH	0.00	\$233.00	0.00	\$0.00	Replace	Check	X	SVC
16361370	60	FAN RADIATOR , LH	0.00	\$181.80	0.00	\$0.00	Replace	Check	X	SVC
16711371	60	FAN SHROUD RADIATOR	0.00	\$219.30	0.00	\$0.00	Replace	Check	X	SVC
16363361	60	MOTOR, COOLING FAN , RH	0.00	\$443.40	0.00	\$0.00	Replace	Check	X	SVC
16363370	60	MOTOR, COOLING FAN , LH	0.00	\$543.50	0.00	\$0.00	Replace	Check	X	SVC
88370470	92	AIR CON COMPRESSOR ASSY	0.00	\$2,887.80	0.00	\$0.00	Replace	Check	X	SVC
88710471	60	TUBE & ACCESSORY	0.00	\$574.40	0.00	\$0.00	Replace	Check	X	SVC
88460103	20	AIR CON CONDENSER ASSY	1.00	\$1,317.70	25.00	\$988.28	Replace	Replace	X	CRU
88703470	80	HOSE SUB-ASSY, DISCHARGE	0.00	\$337.10	0.00	\$0.00	Replace	Check	X	SVC
88704471	00	HOSE SUB-ASSY, SUCTION	0.00	\$541.90	0.00	\$0.00	Replace	Check	X	SVC
88707470	90	PIPE SUB-ASSY, SUCTION	0.00	\$389.60	0.00	\$0.00	Replace	Check	X	SVC
88688477	10	BRACKET, COOLER REFRIGERANT HOSE, NO.1	0.00	\$13.20	0.00	\$0.00	Replace	Check	X	SVC
88688477	00	BRACKET, COOLER REFRIGERANT HOSE, NO.2	0.00	\$18.70	0.00	\$0.00	Replace	Check	X	SVC
164A2370	12	TANK, RESERVE SEALED W/O CAP	0.00	\$127.00	0.00	\$0.00	Replace	Check	X	SVC
16268371	00	PIPE, WATER BY-PASS , NO.1	0.00	\$11.00	0.00	\$0.00	Replace	Check	X	SVC
16296370	10	HOSE, WATER BY-PASS , NO.8	0.00	\$37.90	0.00	\$0.00	Replace	Check	X	SVC
17753370	10	INLET, AIR CLEANER, NO 3	0.00	\$35.30	0.00	\$0.00	Replace	Check	X	SVC
17752371	21	INLET, AIR CLEANER, NO 2	0.00	\$93.90	0.00	\$0.00	Replace	Check	X	SVC
17751371	10	INLET, AIR CLEANER, NO 1	0.00	\$130.50	0.00	\$0.00	Replace	Check	X	SVC
96111106	50	CLAMP (FOR AIR CLEANER INLET, NO.1)	0.00	\$7.10	0.00	\$0.00	Replace	Check	X	SVC
17771370	20	BRACKET, AIR CLEANER	0.00	\$26.90	0.00	\$0.00	Replace	Check	X	SVC
17700373	30	AIR CLEANER ASSY	1.00	\$956.20	25.00	\$717.15	Replace	Replace	X	CRU
28800371	30	BATTERY	0.00	\$1,584.90	0.00	\$0.00	Replace	Check	X	SVC
G9040470	40	INVERTER WATER PUMP ASSY	0.00	\$432.00	0.00	\$0.00	Replace	Check	X	SVC
G922F470	10	HOSE, HV WATER PUMP OUTLET	0.00	\$29.60	0.00	\$0.00	Replace	Check	X	SVC
G922E47	010	HOSE, HV WATER PUMP INLET	0.00	\$37.90	0.00	\$0.00	Replace	Check	X	SVC
G91H047	011	TANK ASSY, INVERTER RESERVE	0.00	\$371.30	0.00	\$0.00	Replace	Check	X	SVC
G922C47	010	HOSE, INVERTER COOLING OUTLET	0.00	\$29.60	0.00	\$0.00	Replace	Check	X	SVC
G922H47	010	HOSE, INVERTER RADIATOR INLET	0.00	\$40.70	0.00	\$0.00	Replace	Check	X	SVC
G922A47	010	HOSE, INVERTER COOLING INLET	0.00	\$43.10	0.00	\$0.00	Replace	Check	X	SVC
G125A47	010	COOLER, MOTOR COOLING	0.00	\$249.10	0.00	\$0.00	Replace	Check	X	SVC
8211147J	21	WIRE, ENGINE ROOM MAIN	0.00	\$6,138.00	0.00	\$0.00	Replace	Check	X	SVC
82123470	60	WIRE, ENGINE, NO.3	0.00	\$260.40	0.00	\$0.00	Replace	Check	X	SVC
821H2470	10	WIRE, AIR CONDITIONER	0.00	\$445.70	0.00	\$0.00	Replace	Check	X	SVC
60117470	20	COVER SUB-ASSY, FRONT PILLAR, UPR RH	0.00	\$96.90	0.00	\$0.00	Replace	Check	X	SVC
60118470	20	COVER SUB-ASSY, FRONT PILLAR, UPR LH	0.00	\$96.90	0.00	\$0.00	Replace	Not Given	X	SVC
53801470	80	FENDER SUB-ASSY, FR , RH	1.00	\$933.10	25.00	\$699.83	Replace	Replace	X	CRU
43212470	40	KNUCKLE, STEERING, LH	0.00	\$555.20	0.00	\$0.00	Replace	Check	X	SVC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 6365592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 05/02/2021

User ID : PohSuan

4504749195	END SET, TIE ROD, LH	0.00	\$155.90	0.00	\$0.00	Replace	Check	X	SVC
4806947060	LOWER ARM SUB-ASSY, FRONT LH	0.00	\$631.60	0.00	\$0.00	Replace	Check	X	SVC
8794047440	MIRROR ASSY, OUTER REAR VIEW, LH	0.00	\$1,283.90	0.00	\$0.00	Replace	Not Given	X	SVC
8794547060A1	COVER, OUTER MIRROR, LH	0.00	\$89.50	0.00	\$0.00	Replace	Not Given	X	SVC
6700147152	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,249.60	100.00	\$0.00	Replace	Repair	X	SVC
	STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	X	NEL
8121047020	LAMP ASSY, FOG, RH	0.00	\$910.20	0.00	\$0.00	Replace	Check	X	SVC
8122047020	LAMP ASSY, FOG, LH	1.00	\$910.20	10.00	\$819.18	Replace	Replace	X	MIS
8118547691	UNIT, HEADLAMP, LH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	X	CRU
8114547691	UNIT, HEADLAMP, RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	X	CRA
8105647690	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1.00	\$486.40	10.00	\$437.76	Replace	Replace	X	CRU
8101647690	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check	X	SVC
5330147110	HOOD SUB-ASSY	1.00	\$938.40	25.00	\$703.80	Replace	Replace	X	CRU
5334147040	INSULATOR, HOOD	1.00	\$393.90	25.00	\$295.43	Replace	Replace	X	CRU
5341047130	HINGE ASSY, HOOD, RH	1.00	\$57.00	25.00	\$42.75	Replace	Replace	X	BT
5342047130	HINGE ASSY, HOOD, LH	1.00	\$57.00	25.00	\$42.75	Replace	Replace	X	BT
5351047140	LOCK ASSY, HOOD	1.00	\$131.10	25.00	\$98.33	Replace	Replace	X	BT
5320547900	SUPPORT S/A UPPER,	1.00	\$364.90	25.00	\$273.68	Replace	Replace	X	BT
5320247901	SUPPORT S/A RH	0.00	\$237.00	0.00	\$0.00	Replace	Check	X	SVC
5320347901	SUPPORT S/A LH	0.00	\$237.00	0.00	\$0.00	Replace	Check	X	SVC
5302847010	SUPPORT SUB-ASSY LOWER	0.00	\$397.40	0.00	\$0.00	Replace	Check	X	SVC
5321347050	SUPPORT, RADIATOR UPPER RH	1.00	\$76.70	25.00	\$57.53	Replace	Replace	X	BT
5321447050	SUPPORT, RADIATOR UPPER LH	1.00	\$76.70	25.00	\$57.53	Replace	Replace	X	BT
8651047050	HORN ASSY, HIGH	0.00	\$112.80	0.00	\$0.00	Replace	Check	X	SVC
8652047030	HORN ASSY, LOW	0.00	\$112.80	0.00	\$0.00	Replace	Check	X	SVC
8659147010	BRACKET, HORN	0.00	\$7.80	0.00	\$0.00	Replace	Check	X	SVC
8656047050	HORN ASSY, SECURITY	0.00	\$112.80	0.00	\$0.00	Replace	Check	X	SVC
8531947170	WIPER WASHER INLET	0.00	\$55.40	0.00	\$0.00	Replace	Check	X	SVC
8531547160	WIPER WASHER JAR	0.00	\$183.60	0.00	\$0.00	Replace	Check	X	SVC
1659237020	GUIDE, RADIATOR AIR,	0.00	\$93.90	0.00	\$0.00	Replace	Check	X	SVC
5315547010	SEAL, RADIATOR GRILLE	0.00	\$40.70	0.00	\$0.00	Replace	Check	X	SVC
5321747030	BRACE, HOOD LOCK SUPPORT	1.00	\$76.20	25.00	\$57.15	Replace	Replace	X	BT
7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace	X	NEL
5387547070	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Check	X	SVC
5385147061	PAD, FR WHEEL RH	0.00	\$57.70	0.00	\$0.00	Replace	Not Given	X	SVC
5370147111	APRON SUB-ASSY, FRONT FENDER, RH	1.00	\$944.20	100.00	\$0.00	Replace	Repair	X	SVC
42611-47450	WHEEL, DISC FRONT	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	X	SVC
4355047020	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given	X	SVC
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X	SVC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 05/02/2021

User ID : PohSuan

6101347010	PILLAR, FRONT BODY, RH	0.00	\$339.40	0.00	\$0.00	Replace	Not Given	X	SUC
8791047450	MIRROR ASSY, OUTER REAR VIEW, RH	0.00	\$1,373.50	0.00	\$0.00	Replace	Not Given	X	SUC
8791547070A1	COVER, OUTER MIRROR, RH	0.00	\$89.50	0.00	\$0.00	Replace	Not Given	X	SUC
5380247100	FENDER SUB-ASSY, FR, LH	1.00	\$933.10	25.00	\$699.83	Replace	Replace		CRU
7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace		Nec
5387647110	LINER, FR FENDER, LH	1.00	\$194.30	25.00	\$145.73	Replace	Replace		CRU
5385247041	PAD, FR WHEEL LH	0.00	\$57.70	0.00	\$0.00	Replace	Not Given	X	SUC
5380847020	SEAL SUB-ASSY, LH	0.00	\$50.20	0.00	\$0.00	Replace	Not Given	X	SUC
5382847070	PROTECTOR, FR FENDER LH	0.00	\$90.40	0.00	\$0.00	Replace	Not Given	X	SUC
5370247101	APRON SUB-ASSY, FRONT FENDER, LH	1.00	\$944.20	100.00	\$0.00	Replace	Repair		
42611-47450	WHEEL, DISC FRONT	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	X	SUC
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X	SUC
4355047020	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given	X	SUC
6101447010	PILLAR, FRONT BODY, LH	0.00	\$339.40	0.00	\$0.00	Replace	Not Given	X	SUC
Total			\$54,324.18		\$16,107.86				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		5141047020	COVER ASSY, ENGINE UNDER CENTER SET	1.00	\$452.80	25.00	\$339.60	Replace	Replace	CRU
		7553547020	MOULDING RH	1.00	\$83.30	25.00	\$62.48	Replace	Replace	CRU
		7553647020	MOULDING LH	1.00	\$83.30	25.00	\$62.48	Replace	Replace	CRU
		5570847230	WIPER GARNISH LOUVER SUB-ASSY	1.00	\$666.90	25.00	\$500.18	Replace	Replace	CRU
		5575447070	WIPER GARNISH SHIELD, COWL WATER, LH	1.00	\$18.90	25.00	\$14.18	Replace	Replace	Mis
		1656337010	SEAL, RADIATOR TO LH	1.00	\$24.80	25.00	\$18.60	Replace	Replace	Nec
		1659537050	GUIDE, RADIATOR AIR, LH	1.00	\$58.80	25.00	\$44.10	Replace	Replace	CRU
		1636137070	FAN RADIATOR, RH	1.00	\$233.00	25.00	\$174.75	Replace	Replace	CRA
		1636137060	FAN RADIATOR, LH	1.00	\$181.80	25.00	\$136.35	Replace	Replace	CRA
		1671137160	FAN SHROUD RADIATOR	1.00	\$219.30	25.00	\$164.48	Replace	Replace	CRA
		1636336160	MOTOR, COOLING FAN, RH	1.00	\$443.40	10.00	\$399.06	Replace	Replace	CRU
		1636337060	MOTOR, COOLING FAN, LH	1.00	\$543.50	10.00	\$489.15	Replace	Replace	CRU
		8870447100	HOSE SUB-ASSY, SUCTION	1.00	\$541.90	25.00	\$406.43	Replace	Replace	Def
		1775237121	INLET, AIR CLEANER, NO 2	1.00	\$93.90	25.00	\$70.43	Replace	Replace	CRU
		1775137110	INLET, AIR CLEANER, NO 1	1.00	\$130.50	25.00	\$97.88	Replace	Replace	CRU
		2880037130	BATTERY	1.00	\$1,584.90	10.00	\$1,426.41	Replace	Replace	CRU
		G91H047011	TANK ASSY, INVERTER RESERVE	1.00	\$371.30	25.00	\$278.48	Replace	Replace	CRU
		5320247901	SUPPORT S/A RH	1.00	\$237.00	25.00	\$177.75	Replace	Replace	BT
		5320347901	SUPPORT S/A LH	1.00	\$237.00	25.00	\$177.75	Replace	Replace	BT
		5302847010	SUPPORT SUB-ASSY LOWER	1.00	\$397.40	25.00	\$298.05	Replace	Replace	BT
		5387547070	LINER, FR FENDER, RH	1.00	\$198.40	25.00	\$148.80	Replace	Replace	Cut
		1230537340	INSULATOR SUB-ASSY, ENGINE MOUNTING, RH	1.00	\$382.60	25.00	\$286.95	Replace	Replace	BT
		1237237311	INSULATOR, ENGINE MOUNTING, LH	1.00	\$258.00	25.00	\$193.50	Replace	Replace	BT
		7440447030	CLAMP SUB-ASSY, BATTERY	1.00	\$41.40	25.00	\$31.05	Replace	Replace	CRU
		5570147070	PANEL SUB-ASSY, COWL TOP, OUTER	1.00	\$416.10	25.00	\$312.08	Replace	Replace	CRU
Total					7,900.20		6,310.97			