



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2104543

INV Date 29/06/2021

Reference CC4/FCI21000271/R1ea3q2

Code FCI2

### PROFESSIONAL SERVICE FEE

Vehicle No. SLR 3494B  
Insured Veh. SHA 8681G  
Claim No. D21000121MFSH/1  
Policy No. D-20094921MFSH  
Accident Date 16/12/2021  
Inspection Date 08/01/2021

Description	Total
Survey Inspection	223.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>223.00</b>
<b>GST (7%)</b>	<b>15.61</b>
<b>Grand Total</b>	<b>238.61</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21000271/R1ea3q2	
			Date: 29/06/2021	
			Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHA 8681G	Veh. Inspected	SLR 3494B
	Policy No.	D-20094921MFSH	Coverage (\$)	0.00
	Claim No.	D21000121MFSH/1	Excess (\$)	0.00
	Assign From	ERIC WOO	Assign Date	06/01/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	BYD E6H	c.c	0
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	LC0CE4DB5G1018912	Colour	WHITE
	Odometer	49861 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/65 R17	ROADSTONE	6 mm
	L/H Front Tyre	225/65 R17	ROADSTONE	6 mm
	R/H Rear Tyre	225/65 R17	ROADSTONE	6 mm
	L/H Rear Tyre	225/65 R17	ROADSTONE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	16/12/2021	Inspection Date	08/01/2021
	Survey held at	31 CORPORATION ROAD		
	Repairer	DING AUTOMOTIVE PTE LTD		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 3494B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REPAIR FRONT BUMPER (NPA)	TO REPAIR SEE LABOUR	-	-
1	REPAIR FRONT FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
			-	-
	<b><u>LABOUR</u></b>			
	STRAIGHT AND PANEL BEAT ACCIDENT AREA.INCLUSIVE OF THE REPAIR REPAIR FRONT BUMPER AND REPAIR FRONT FENDER LH.		450.00	250.00
	RESPRAY FRONT BUMPER.		250.00	200.00
	RESPRAY FRONT FENDER LH .		250.00	200.00
	RESPRAY FRONT WHEEL RIM LH .	NOT NECESSARY	200.00	-
			1,150.00	650.00
<b>GRAND TOTAL</b>			<b>1,150.00</b>	<b>650.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>650.00</b>

Report Ref No. CC4/FCI21000271/R1ea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SLR 3494B

### INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SLR 3494B

### RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

