

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

06/01/2021 13:58

JOB-NO: 85008860

Page 1 of 1

OWNER'S PARTICULARS

NAME: SEV PTE LTD (Fleet)

CONTACT:

ADDRESS: 152 UBI AVENUE 4
SINGAPORE (408826)

rakshan-rai@sev.com.sg

VEHICLE DETAILS

LICENSE NO: SLR3494B

TRANS: AUTO

CHASSIS: LC0CE4DB5G1018912

MAKE / MODEL: BYD / e6

ENGINE: BYDTC90B115000107

OWNER'S INSURER: AVIVA Ltd.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	MARK UP	MARKUP PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHT AND PANEL BEAT ACCIDENT AREA	1.00	450.00	0.00	450.00		Y	250
2 RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00		Y	200
3 RESPRAY FRONT FENDER LH	1.00	250.00	0.00	250.00		Y	200
4 RESPRAY FRONT WHEEL RIM LH	1.00	200.00	0.00	200.00		Y	X
TOTAL:		1,150.00	0.00	1,150.00			
MATERIALS							
1 REPAIR FRONT BUMPER <i>Repair</i>	1.00	0.00	0.00	0.00		Y	
2 REPAIR FRONT FENDER LH <i>Repair</i>	1.00	0.00	0.00	0.00		Y	
TOTAL:		0.00	0.00	0.00			
TOTAL PARTS & LABOUR :		1,150.00	0.00	1,150.00			

EXCESS/LOADING:S\$ 0.00

No. Of Day:

*2 days*RE-SURVEY ~~BEFORE~~ AFTER PAINTING

PART-BY-PART OR LUMP SUM: S\$

DATE OF SURVEY: *08 / 01 / 2021 @ 1050*

SURVEYED BY:

RKau

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray paint
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

G-STAR-WI-ET-001-02-Rev00