

Date: 04.01.2021
Vehicle No: SMM7920B
Model: HONDA SHUTTLE HYBRID 1.5
Chassis: GP72008772-2019
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SMQ9491M
Date of Accident: 31.12.2020

*Not Authorized
McRory B4 painting 4 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>By</i> \$1,193.00 ✓
2	REAR TAILGATE "HYBRID" EMBLEM	1		<i>na</i> \$75.80 ✓
3	REAR TAILGATE "SHUTTLE" EMBLEM	1		<i>na</i> \$65.60 ✓
4	REAR TAILGATE LOGO EMBLEM	1		<i>na</i> \$58.20 ✓
5	REAR WINDSCREEN MOULDING	1		<i>na</i> \$118.70 ✓
6	REAR END PANEL UPPER COVERING	1		<i>na</i> \$155.50 ✗
7	REAR BUMPER	1		<i>na</i> \$950.80 ✗
8	REAR END PANEL	1		REPAIR
SUB TOTAL				\$2,617.60
LESS 20%				-\$523.52
PARTS TOTAL				\$2,094.08

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		<i>na</i> \$80.00 ✓
2	REAR TAILGATE INNER TRIME CLIPS	1		<i>na</i> \$40.00 ✗
3	REAR END PANEL UPPER COVERING CLIPS	1		<i>na</i> \$30.00 ✗
4	REAR BUMPER REVERSE SENSOR	1		\$300.00 ✓
5	REAR BUMPER CLIPS	1		<i>na</i> \$50.00 ✗
S/N TOTAL				\$500.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

300
\$700.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR END PANEL, REAR BUMPER & ETC.

400
\$700.00

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC. TO EFFECT REPLACE OF REAR TAILGATE.

120
\$150.00

Head office

6 Kung Chong Road Singapore 159143
Tel (+65) 6472 1313 | Fax (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel (+65) 6484 0010 | Fax (+65) 6481 1903

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel (+65) 6481 1522 | Fax (+65) 6481 1011



Date: 04.01.2021
 Vehicle No: SMM7920B
 Model: HONDA SHUTTLE HYBRID 1.5
 Chassis: GP72008772-2019
 Reg.Year: 2019

Third Party Insurer: AIG
 Third Party Veh No: SMQ9491M
 Date of Accident: 31.12.2020

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERTAIONS. \$120.00 601

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC. \$100.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$80.00 151

LABOUR TOTAL \$1,850.00

TingAn TOTAL \$4,444.08

