

Date: 04.01.2021
Vehicle No: SMM7920B
Model: HONDA SHUTTLE HYBRID 1.5
Chassis: GP72008772-2019
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SMQ9491M
Date of Accident: 31.12.2020

8 2344.04

Not Authorized
Repair by painting 4 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		By \$1,193.00 ✓
2	REAR TAILGATE "HYBRID" EMBLEM	1		na \$75.80 ✓
3	REAR TAILGATE "SHUTTLE" EMBLEM	1		na \$65.60 ✓
4	REAR TAILGATE LOGO EMBLEM	1		na \$58.20 ✓
5	REAR WINDSCREEN MOULDING	1		na \$118.70 ✓
6	REAR END PANEL UPPER COVERING	1		na \$155.50 X
7	REAR BUMPER	1		na \$950.80 X
8	REAR END PANEL	1		REPAIR
SUB TOTAL				\$2,617.60
LESS 20%				-\$523.52
PARTS TOTAL				\$2,094.08

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		na \$80.00 ✓
2	REAR TAILGATE INNER TRIME CLIPS	1		na \$40.00 X
3	REAR END PANEL UPPER COVERING CLIPS	1		na \$30.00 X
4	REAR BUMPER REVERSE SENSOR	1		Shoy \$300.00 200JN
5	REAR BUMPER CLIPS	1		na \$50.00 X
S/N TOTAL				\$500.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

300J

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR END PANEL, REAR BUMPER & ETC.

400J

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC. TO EFFECT REPLACE OF REAR TAILGATE.

\$150.00 120J

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____
Date: _____

Date: 04.01.2021
Vehicle No: SMM7920B
Model: HONDA SHUTTLE HYBRID 1.5
Chassis: GP72008772-2019
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SMQ9491M
Date of Accident: 31.12.2020

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM &
ETC. BACK TO ORIGINAL OPERTAIONS.

\$120.00 601

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

~ \$100.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$80.00 151

LABOUR TOTAL \$1,850.00

TingAn

TOTAL \$4,444.08

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

