

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : HE WEIQING DAWN
BLK 615A EDGEFIELD PLAINS #16-331

SINGAPORE 821615

ATTN:

Estimate No: MC1901673
Date: 05 Jan 2021
Policy No: PNPV2019-00000672-01
Veh Reg No: SKH7062C
Make/Model: VOLKSWAGEN
TOURAN 1.4 TSI AT
1T32B4

Your Ref No: -
Claim Type: Third Party
Accident Date: 05/01/2021
TP Veh Reg No: SJM8815B

Estimate Repair Cost to Vehicle No :SKH7062C

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 FRONT FENDER RH	1 PC	608.45	
2 FRONT FENDER COWLING RH	1 PC	170.15	
3 FRONT FENDER COWLING CLIPS	1 PC	2.50	
4 FRONT BUMPER	1 PC	1,056.95	
5 FRONT BUMPER SIDE RETAINER RH	1 PC	69.85	
6 FRONT BUMPER CLIPS	12 PC	30.00	
7 HEADLAMP RH WITH LOWER BEAM	1 PC	627.05	
8 FRONT WHEEL BEARING RH WITH HUB	1 PC	491.60	
9 SPORT RIM RHF	1 PC	1,209.95	
		4,266.50	
	Less 10%	426.65	3,839.85
Special Nett			
10 TYRE RHF -CHECK PRICE	1 PC	0.0000	
		0.00	0.00
LABOUR			
11 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
12 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	
13 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	60.00	
14 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	1 PC	120.00	
15 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	
16 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR FRONT INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	
17 TO SPRAY FRONT FENDER RH, FRONT BUMPER	1 PC	500.00	
		1,360.00	1,360.00

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : HE WEIQING DAWN
BLK 615A EDGEFIELD PLAINS #16-331

SINGAPORE 821615

ATTN:

Estimate No: MC1901673
Date: 05 Jan 2021
Policy No: PNPV2019-00000672-01
Veh Reg No: SKH7062C
Make/Model: VOLKSWAGEN
TOURAN 1.4 TSI AT
1T32B4

Your Ref No: -
Claim Type: Third Party
Accident Date: 05/01/2021
TP Veh Reg No: SJM8815B

Estimate Repair Cost to Vehicle No :SKH7062C


Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		Total	S\$ 5,199.85
		Add GST @ 7%	363.99
		Total Amount Payable	S\$ 5,563.84

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND FIVE HUNDRED SIXTY THREE AND CENTS EIGHTY FOUR ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE