

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0001/2021/NS
DATE : 4-Jan-21
WIP : 65366

VEHICLE IN IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian, Rasul

6 days - ok - jb - 15 Mar 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR CHAN WHYE QUINE
ADDRESS : 1 UPPER BUKIT TIMAH VIEW
#02-08
SINGAPORE 588132
TELEPHONE : HP +65 97316113
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070133655
VEHICLE NO : **SMV 4435 H**
MODEL CODE : AUDI A3 SPORTBACK 1.4 TFS
MODEL YEAR : 30/9/2020
ENGINE NO : CZE 866053
CHASSIS NO : WAUZZZ8V4LA083364
MILEAGE : 26920KM
DATE IN : 2-Jan-21
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 31-Dec-20
PLACE OF ACCIDENT : UPPER BUKIT TIMAH ROAD, JUST OUTSIDE
UPPER BUKIT TIMAH VIEW ENTRANCE

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 4435 H

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY.	S/N \$	350.00	
4	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$	2,400.00	\$ 1,200.00
SUB TOTAL LABOUR CHARGES		:	\$ 3,460.00	\$ 1,200.00

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 4435 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>c/f</i>		\$ 1,200.00
5	TO DISMANTLE FRONT BUMPER AND RHS FRONT FENDER. TO RENEW RHS FRONT FENDER AND RHS HEADLIGHT. TO REPAIR RHS FRONT DOOR AND RHS SILL PANEL. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00	\$ 1,000.00
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER RHS FRONT DOOR AND RHS SILL PANEL.	\$ 3,600.00	\$ 1,100.00
7	TO RENEW RHS FRONT RIM. TO CARRY OUT PRE AND POST WHEEL ALIGNMENT.	S/N \$ 520.00	\$ 520.00
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 10,572.00	\$ 4,012.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 4435 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER GUIDE SECTION - RH	\$	38.00	
2	FRONT FENDER - RH	\$	841.00	\$ 680.40
3	FRONT FENDER ATTACHMENT OARTS	\$	71.00	
4	FRONT FENDER CLOSING ELEMENT - RH	\$	61.00	\$ 48.88
5	FRONT FENDER BRACKET - OUTER	\$	47.00	\$ 37.68
6	FRONT FENDER BRACKET - INNER	\$	27.00	\$ 21.84
7	FRONT FENDER BRACE	\$	95.00	
8	WHEEL HOUSING LINER	\$	167.00	
9	WHEEL HOUSING LINER ATTACHMENT PARTS	\$	57.00	
10	LED HEADLIGHT - RH	\$	5,455.00	
11	FRONT ALUMINIUM RIM - RH	\$	746.00	\$ 596.80
12	TRACK CONTROL ARM	\$	363.00	\$ 298.00
13	WHEEL BEARING HOUSING	\$	563.00	\$ 462.80
14	WHEEL BEARING	\$	485.00	\$ 382.40
15	GUIDE JOINT - RH	\$	120.00	\$ 98.80
16	COUPLING ROD	\$	93.00	
17	STABILIZER BAR	\$	384.00	
18	DRIVE SHAFT - RH	\$	2,118.00	
19	GAS SHOCK ABSORBER	\$	259.00	
20	TRACK ROD	\$	89.00	\$ 73.04
SUB TOTAL SPARE PARTS		:	\$ 12,079.00	\$ 2,700.64

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 4435 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 2,700.64
21	TIE ROD END - RH	\$	122.00	\$ 97.20
22	ASSEMBLY CARRIER	\$	972.00	
23	RUBBER BUSHES SET - UPPER/LOWER	\$	170.00	
24	Added parts -see attached	\$	50.00	\$ 36.16
25	SUNDRIES	\$	300.00	\$ 126.80
TOTAL SPARE PARTS		:	\$ 13,693.00	\$ 2,960.80
TOTAL LABOUR CHARGES		:	\$ 10,572.00	\$ 4,012.00
GRAND TOTAL		:	\$ 24,265.00	\$ 6,972.80

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0001/2021/NS 14-Jan-21 CHANG 1 of 1 SMV 4435 H AUDI A3 SPORTBACK 1.4 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	STEERING GEAR REPAIR KIT	\$ 50.00	\$	36.16
	GRAND TOTAL	\$ 50.00	\$	36.16

For Premium Automobiles Pte Ltd

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT