

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0002/2020/NS
DATE : 4-Jan-21
WIP : 65288

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian

13 days exclude 2 Sundays

jb 16 Mar 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR SIOW TZE HOU, EUGENE(XIAO ZHIHAO, EUGENE)
ADDRESS : BLK 273 COMPASSVALE LINK
#14-176
SINGAPORE 544273
TELEPHONE : HP +65 97616972
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800055765-01
VEHICLE NO : **SLZ 7861 G**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 18/5/2018
ENGINE NO : CVK 058692
CHASSIS NO : WAUZZZF47JA147193
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Jan-21
PLACE OF ACCIDENT : HOUGANG AVE 3 AND TAMPINES RD JUNCTION

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLZ 7861 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$	360.00	\$	360.00
2	TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$	600.00	\$	600.00
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND 1/4 GLASS.	S/N \$	400.00	\$	400.00
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	\$	150.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	S/N \$	1,400.00	\$	1,400.00
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,400.00	\$	1,400.00
SUB TOTAL LABOUR CHARGES		:	\$ 4,360.00	\$	<u>4,310.00</u>

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLZ 7861 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 4,310.00
7	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N	\$ 280.00	\$ 280.00
8	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. CUT OUT AND WELD RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 5,600.00	\$ 3,500.00
9	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, DOOR HANDLE, RHS SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.		\$ 5,550.00	\$ 3,125.00
10	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N	\$ 280.00	\$ 280.00
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 16,262.00	\$ 11,687.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 7861 G

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR BUMPER		\$ 2,181.00	
2	REAR BUMPER FIXING PARTS		\$ 72.00	
3	REAR BUMPER GUIDE SECTION - RH		\$ 45.00	
4	REAR FENDER - RH		\$ 2,644.00	\$ 2,115.20
5	REAR WINDSCREEN		\$ 1,141.00	\$ 912.80
6	1/4 GLASS - RH		\$ 609.00	\$ 486.80
7	PRIMER		\$ 19.00	\$ 14.96
8	REAR DOOR - RH		\$ 2,354.00	\$ 1,883.20
9	REAR DOOR OUTER SEAL - RH	NEC	\$ 203.00	\$ 162.00
10	BONDING AGENT	NEC	\$ 47.00	
11	CLEANING SOLUTION	NEC	\$ 65.00	
12	REAR DOOR SEALING STRIP		\$ 16.00	
13	REAR DOOR ATTACHMENT PARTS		\$ 563.00	
14	REAR DOOR CATCH		\$ 119.00	
15	REAR DOOR HANDLE TRIM PLATE - RH		\$ 87.00	
16	REAR ALUMINIUM RIM - RH		\$ 684.00	
17	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	\$ 200.00
18	1/4 GLASS SEALANT	S/N	\$ 100.00	\$ 100.00
19	METAL FILLER POWDER	S/N	\$ 280.00	\$ 280.00
20	STONE CHIP	S/N	\$ 180.00	\$ 180.00
21	CAVITY WAX	S/N	\$ 140.00	\$ 140.00
22	ACRYLIC SEALANT	S/N	\$ 180.00	\$ 180.00
23	SUNDRIES		\$ 300.00	\$ 43.68
TOTAL SPARE PARTS		:	\$ 12,229.00	\$ 6,698.64
TOTAL LABOUR CHARGES		:	\$ 16,262.00	\$ 11,687.00
GRAND TOTAL		:	\$ 28,491.00	\$ 18,385.64

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT