



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2104203
INV Date 14/06/2021
Reference CC4/LPC21000286/Bba3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMC 4868S
Insured Veh. YM 6777M
Claim No. 19/20/21/VC05/024096
Policy No. Z/21/VC00/109692
Accident Date 06/01/2021
Inspection Date 07/01/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CC4/LPC21000286/Bba3q2

Date: 14/06/2021

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 6777M	Veh. Inspected	SMC 4868S
Policy No.	Z/21/VC00/109692	Coverage (\$)	0.00
Claim No.	19/20/21/VC05/024096	Excess (\$)	0.00
Assign From	GERALD	Assign Date	06/01/2021

2. Vehicle Particulars & Condition

Make & Model	KIA FORTE K3 1.6	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KNAFJ411MJ5766212	Colour	WHITE
Odometer	90402 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	POOR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	KUMHO	5 mm
L/H Front Tyre	225/45 R17	KUMHO	5 mm
R/H Rear Tyre	225/45 R17	KUMHO	5 mm
L/H Rear Tyre	225/45 R17	KUMHO	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/01/2021	Inspection Date	07/01/2021
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **10 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 4868S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	DENTED	835.10	835.10
1	BONNET INSULATOR	NO SUCH PARTS	141.60	-
1	BONNET LOCK ASSY	NOT DAMAGED	68.00	-
2	BONNET HINGE @\$68.00	NOT DAMAGED	136.00	-
1	FRONT BUMPER	BROKEN	639.50	639.50
1	FRONT BUMPER LOGO	CUT	78.00	38.00
1	FRONT BUMPER CENTRE GRILLE	BROKEN	428.00	262.00
1	FRONT BUMPER LOWER GRILLE	BROKEN	170.00	170.00
1	FRONT NO LICENSE PLATE	REPEATED	75.00	-
2	FRONT BUMPER SIDE RETAINER @\$42.10	NECESSARY	84.20	84.20
1	FRONT BUMPER INNER SPONGE	BROKEN	184.00	84.00
1	FRONT BUMPER REINFORCEMENT	BENT	496.80	496.80
1	FRONT BUMPER TOP CAP	NOT DAMAGED	68.00	-
2	FRONT FOG LAMP @\$241.00	NO SUCH PARTS	482.00	-
2	FRONT FOG LAMP GARNISH @\$79.20	N/S BROKEN	158.40	79.20
1	FRONT PANEL (RADIATOR)	BENT	675.50	469.00
2	FRONT FENDER @\$443.60	NOT DAMAGED	887.20	-
2	FRONT FENDER INNER COWLING @\$195.00	NOT DAMAGED	390.00	-
2	HEADLAMP @\$2209.00	BROKEN	4,418.00	4,418.00
2	HEADLAMP LOWER BRACKET @\$86.10	NO SUCH PARTS	172.20	-
1	FRONT AIR DUCT	NOT DAMAGED	145.00	-
1	A/C CONDENSER	BENT	774.00	681.00
1	A/C CONDENSER HIGH PRESSURE PIPE	NOT DAMAGED	591.00	-
1	A/C CONDENSER LOW PRESSURE PIPE	NOT DAMAGED	122.00	-
1	A/C COMPRESSER	NOT DAMAGED	1,418.00	-
1	RADIATOR	NOT DAMAGED	498.00	-
1	RADIATOR TOP HOSE	NOT DAMAGED	58.00	-
1	RADIATOR LOWER HOSE	NOT DAMAGED	68.00	-
1	COOLING FAN MOTOR ASSY	BROKEN	546.80	479.00
1	WIPER WASHER TANK	NOT DAMAGED	88.00	-
1	WIPER WASHER TANK MOTOR	NOT DAMAGED	54.00	-

Report Ref No. CC4/LPC21000286/Bba3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOTLID	DENTED	938.00	938.00
1	BOOTLID LOGO	NECESSARY	48.00	48.00
1	BOOTLID EMBLEM 'CERATO'	NECESSARY	52.00	43.20
1	BOOTLID EMBLEM 'K3'	NECESSARY	45.00	36.70
1	BOOTLID EMBLEM 'C&C'	NECESSARY	74.00	25.00
2	BOOTLID NO PLATE LAMP @\$65.00	NOT DAMAGED	130.00	-
2	BOOTLID LAMP @\$422.00	BROKEN	844.00	810.00
1	BOOTLID LOCK	JAMMED	118.00	118.00
1	BOOTLID LOCK STRIKER	NOT DAMAGED	48.00	-
1	BOOTLID WEATHERSTRIP	DISTORTED	198.00	145.00
1	BOOTLID INNER TRIM BOARD	NOT DAMAGED	163.00	-
2	BOOTLID HINGE @\$68.50	BENT	137.00	137.00
1	REAR BUMPER	BROKEN	698.50	698.50
2	REAR BUMPER SIDE RETAINER @\$62.00	NECESSARY	124.00	70.00
1	REAR BUMPER REINFORCEMENT	BROKEN	343.80	304.00
2	REAR BUMPER REINFORCEMENT BRACKET @\$188.00	BENT	376.00	126.00
1	REAR BUMPER DIFFUSER	BROKEN	387.50	258.00
2	REAR BUMPER REFLECTOR @\$109.80	BROKEN	219.60	66.20
1	REAR END PANEL	DENTED	472.60	324.80
1	REAR END PANEL TOP GARNISH	BROKEN	118.50	84.00
1	SPARE TYRE PANEL	DENTED	608.50	608.50
1	SPARE TYRE TOP BOARD	NOT DAMAGED	255.00	-
1	SPARE TYRE PANEL TOP TOOL SPONGE	NOT DAMAGED	210.40	-
1	SPARE TYRE PANEL WHEEL NUT	NOT DAMAGED	38.00	-
2	REAR FENDER @\$1183.30	NOT DAMAGED	2,366.60	-
2	REAR FENDER INNER TRIM @\$216.00	TORN	432.00	432.00
2	REAR FENDER INNER COWLING @\$148.00	NOT DAMAGED	296.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	130.00	-
2	TAIL LAMP @\$453.80	BROKEN	907.60	907.60
2	TAIL LAMP BASE PANEL @\$228.60	DENTED	457.20	200.00
2	TAIL LAMP LOWER BRACKET @\$166.00	NO SUCH PARTS	332.00	-
1	REAR EXHAUST	NOT DAMAGED	684.30	-
2	REAR EXHAUST MOUNTING @\$48.00	NOT DAMAGED	96.00	-

Report Ref No. CC4/LPC21000286/Bba3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-2,729.94	-1,511.63
			24,569.46	13,604.67
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NOT NECESSARY	80.00	-
1	BONNET SEALANT (SN)	NECESSARY	100.00	30.00
1	BONNET INSULATOR CLIPS (SN)	NOT NECESSARY	50.00	-
1	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT BUMPER CENTRE GRILLE CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT BUMPER LOWER GRILLE CLIPS (SN)	NECESSARY	50.00	30.00
2	FRONT FOG LAMP GARNISH CLIPS @\$50.00 (SN)	NOT NECESSARY	100.00	-
2	FRONT FENDER SEALANT @\$100.00 (SN)	NOT NECESSARY	200.00	-
2	FRONT FENDER INNER COWLING CLIPS @\$50.00 (SN)	NOT NECESSARY	100.00	-
1	FRONT NUMBER PLATE W/COWLING (SN)	BENT	80.00	80.00
1	A/C FLUID (SN)	NECESSARY	80.00	60.00
1	RADIATOR COOLANT (SN)	NECESSARY	80.00	40.00
1	BOOTLID SEALANT (SN)	NECESSARY	100.00	30.00
1	BOOTLID LAMP CLIPS (SN)	NOT NECESSARY	50.00	-
2	BOOTLID LAMP SEAL @\$60.00 (SN)	NECESSARY	120.00	60.00
1	BOOTLID INNER TRM BOARD CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR BUMPER DIFFUSER CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR END PANEL SEALANT (SN)	NECESSARY	100.00	30.00
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	50.00	30.00
1	SPARE TYRE PANEL SEALANT (SN)	NECESSARY	100.00	30.00
2	REAR FENDER SEALANT @\$100.00 (SN)	NOT NECESSARY	200.00	-
2	REAR FENDER INNER TRIM CLIPS @\$50.00 (SN)	NECESSARY	100.00	60.00
2	REAR FENDER INNER COWLING CLIPS @\$50.00 (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SEAL (SN)	NOT NECESSARY	60.00	-
1	REAR WINDSCREEN PRIMER AND CLEANER (SN)	NOT NECESSARY	80.00	-
2	TAIL LAMP CLIPS @\$50.00 (SN)	NOT NECESSARY	100.00	-
2	TAIL LAMP SEAL @\$60.00 (SN)	NECESSARY	120.00	60.00
2	TAIL LAMP BASE PANEL SEALANT @\$100.00 (SN)	NECESSARY	200.00	40.00

Report Ref No. CC4/LPC21000286/Bba3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE W/COWLING (SN)	NOT DAMAGED	80.00	-
1	REAR REVERSE CAMERA (SN)	NOT DAMAGED	480.00	-
2	REAR BUMPER REVERSE SENSORS @\$250.00 (SN)	SCRATCHED	500.00	200.00
			3,810.00	900.00
	LABOUR			
	R&R BONNET COMPONENT .		150.00	30.00
	FRONT CHECK WIRING .		100.00	30.00
	R&R CONDENSER .		150.00	80.00
	R&R RADIATOR.		150.00	80.00
	FRONT UPHOLSTERY .	NOT NECESSARY	300.00	-
	FRONT PANEL BEARING .		1,400.00	600.00
	FRONT RUST PROOFING .	NOT NECESSARY	200.00	-
	FRONT SPRAY PAINTING .		1,400.00	400.00
	DIAGNOSTIC RESET FAULT CODE.		300.00	120.00
	R&R BOOTLID COMPONENT.		150.00	80.00
	R&R REVERSE CAMERA.	NOT NECESSARY	100.00	-
	R&R REAR BUMPER REVERSE SENSOR .		100.00	60.00
	R&R FUEL FILLER PIPE .	NOT NECESSARY	150.00	-
	R&R REAR WINDSCREEN .	NOT NECESSARY	150.00	-
	R&R EXHAUST PIPE .	NOT NECESSARY	150.00	-
	REAR UPHOLSTERY .	NOT NECESSARY	300.00	-
	REAR PANEL BEATING.		1,800.00	1,200.00
	REAR RUST PROOFING .		200.00	80.00
	REAR SPARE PAINTING .		1,800.00	1,000.00
			9,050.00	3,760.00
	GRAND TOTAL		37,429.46	18,264.67
RECOMMENDED COST OF REPAIRS				18,264.67

Report Ref No. CC4/LPC21000286/Bba3q2

LIM TEOW GUAN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMC 4868S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R









LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMC 4868S

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

