



TAN LIM MOTOR PTE LTD

AlGAsia Insured's Veh No : SFY2046C

Date of Accident : 01 January 2021

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs Jeeka

Date : 04 January 2021

Estimate To Repair SKE3158C - Toyota Prius C CVT

Chassis No : JTDKD3B3801001512

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper	\$ 645.00
02	2 ps	rear bumper side retainer @ \$66.00	\$ 132.00
03	1 pc	rear bumper reinforcement	\$ 396.00
04	2 ps	rear bumper reinforcement bracket @ \$98.90	\$ 197.80
05	2 ps	taillamp @ \$250.00	\$ 500.00
06	6 ps	taillamp clips @ \$4.30	\$ 25.80
07	6 ps	taillamp clip holder @ \$4.30	\$ 25.80
08	1 pc	tailgate lid lock	\$ 374.00
09	1 pc	tailgate lid Toyota emblem badge	\$ 39.60
10	1 pc	tailgate lid centre logo badge	\$ 47.90
11	1 pc	tailgate lid Prius C emblem	\$ 44.00
12	1 pc	tailgate lid Hyundai emblem	\$ 83.00
13	1 pc	tailgate lid weatherstrip	\$ 242.00
14	1 pc	rear end panel	\$ 580.00
15	1 pc	rear end panel top garnish	\$ 188.20
			\$ 3,521.10
		Less 25 %	\$ 880.27
			\$ 2,640.83
		<u>LABOUR & MISC. CHARGES</u>	
01		To check electrical lighting concerned.	\$ 50.00
02		To reinstall of rear bumper parking sensor.	\$ 60.00
03		To rust-proofing of the affected areas.	\$ 70.00
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 700.00
05		Putty and spray painting of the affected portion.	\$ 750.00
			\$ 1,630.00
		Total	\$ 4,270.83

not Authorized

2/1/21

3 days

2/5 \$
take photo of the damage

req: Marcus - L46

07/01/2021 CO9000

20/02

✓

X

7

7

X

X

X

X

X

X

X

X

X

7

7

20

50

7

7

400