



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21000291/Uqd3q2	
			Date: 19/01/2021	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLM 3352D	Veh. Inspected	SMM 9207P	
Policy No.	D20MTPV01008792	Coverage (\$)	0.00	
Claim No.	CMTD2100055/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	07/01/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ A200 (A)	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WDD1760432J099565	Colour	GREY	
Odometer	74663 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	235/40 ZR18	PIRELLI	7 mm	
L/H Front Tyre	235/40 ZR18	PIRELLI	7 mm	
R/H Rear Tyre	235/40 ZR18	PIRELLI	7 mm	
L/H Rear Tyre	235/40 ZR18	PIRELLI	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	06/01/2020	Inspection Date	07/01/2021	
Survey held at	H S AUTOMOTIVE SERVICES 2 KAKI BUKIT AVE 2 #01-15 KAKI BUKIT AUTOHUB SINGAPORE 417921			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	