

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 5-Jan-21

INSURANCE: AIG

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA 1550 Y

Description	Qty	List Price	Amount	
Front Bumper Cover <i>cut / mending crack</i>	1	\$ 418.30	\$ 418.30	✓
Front Bumper Bracket (LH/RH) <i>src</i>	2	\$ 28.00	\$ 56.00	X
Headlamp(LH) <i>cut / scratched</i> 2397.60	1	\$ 3,987.30	\$ 3,987.30	✓
Front Fender(LH) <i>Dent</i>	1	\$ 490.70	\$ 490.70	✓
Frt Door(LH) <i>cut / Dent</i>	1	\$ 1,797.20	\$ 1,797.20	✓
Front Door Mirror Holder (LH) <i>HH</i>	1	\$ 175.90	\$ 175.90	X
Front Door Mirror Lamp (LH) <i>HH</i>	1	\$ 97.10	\$ 97.10	X
Rear Door (LH) <i>cut / Dent</i>	1	\$ 1,789.90	\$ 1,789.90	✓
Rear Door Hinge Lower (LH) <i>HH</i>	1	\$ 170.50	\$ 170.50	X
Rear Door Check(LH) <i>HH</i>	1	\$ 85.92	\$ 85.92	X
Rear Door Trim Board (LH) <i>HH</i>	1	\$ 613.60	\$ 613.60	X
Door Centre Pillar Outer (LH) <i>HH</i>	1	\$ 3,764.90	\$ 3,764.90	X
Rocker Panel Outer Garnish <i>cut</i> 290.00	1	\$ 715.60	\$ 715.60	✓
Front Wheel Rim (LH) <i>2. HH / distorted</i>	1	\$ 1,124.20	\$ 1,124.20	2. ✓
Front Wheel Hub Cap and hub assy (LH) <i>2. HH / distorted</i>	1	\$ 678.50	\$ 678.50	2. ✓ 454.00
Front Wheel Hub Cap <i>cut</i>	1	\$ 346.40	\$ 346.40	✓
Front Shock Absorber(Assy)(LH) <i>2. HH / distorted</i> 372.50	1	\$ 372.50	\$ 372.50	2. ✓
Front Shock Absorber Mounting (LH) <i>HH</i>	1	\$ 372.50	\$ 372.50	X
Front Drive Shaft (LH) <i>HH</i>	1	\$ 1,136.70	\$ 1,136.70	X
Front drive shaft extension RH <i>HH</i>	1	\$ 1,125.80	\$ 1,125.80	X
Rack & Pinion Assy <i>HH</i>	1	\$ 1,087.40	\$ 1,087.40	X
STG Tie Rod <i>HH</i>	1	\$ 125.60	\$ 125.60	X
STG Tie End <i>HH</i>	1	\$ 94.70	\$ 94.70	X
Stabilizer Bar <i>HH</i>	1	\$ 326.80	\$ 326.80	X
Stabilizer Bar Link <i>HH</i>	1	\$ 92.10	\$ 92.10	X
Front Suspension Lower Arm (LH) <i>2. HH / distorted</i> 296.80	1	\$ 596.80	\$ 596.80	2. ✓
Knuckle Arm (LH) <i>2. HH / distorted</i> 363.60	1	\$ 663.60	\$ 663.60	2. ✓
ABS Sensor <i>HH</i>	1	\$ 290.00	\$ 290.00	X
Rear Bumper <i>Repair end / mending broken</i> Repair	1	\$ 459.40	\$ 459.40	X
Rear Bumper Cover Clips <i>src</i>	1	\$ 22.00	\$ 22.00	X
Rear Fender(LH) <i>Dent</i>	1	\$ 1,768.30	\$ 1,768.30	✓
Rear Tyre Rim (LH) <i>HH / distorted</i>	1	\$ 1,124.20	\$ 1,124.20	2. ✓
Rear Wheel Hup-Cap (LH) <i>cut</i>	1	\$ 346.40	\$ 346.40	✓
Rear Wheelbearing & Hub assy <i>Dent</i> 454.00	1	\$ 554.00	\$ 554.00	✓
Rear Trailing Arm(LH) <i>distorted</i>	1	\$ 265.40	\$ 265.40	✓
Rear Assist (LH) <i>distorted</i>	1	\$ 227.90	\$ 227.90	✓
Rear shock Absorber(LH) <i>distorted</i>	1	\$ 230.50	\$ 230.50	✓
Rear Shock Absorber Mounting (LH) <i>HH</i>	1	\$ 133.10	\$ 133.10	X
Rear Absorber stopper (LH) <i>HH</i>	1	\$ 137.60	\$ 137.60	X
Rear Absorber Ccp <i>HH</i>	1	\$ 175.60	\$ 175.60	X
Stabilizer Bar <i>HH</i>	1	\$ 387.30	\$ 387.30	X
Stabilizer Link (LH) <i>HH</i>	1	\$ 147.30	\$ 147.30	X

Rear Upper Arm(LH) <i>distorsi</i>	1	\$ 239.50	\$ 239.50	✓
Rear Lower Arm(LH) <i>distorsi</i>	1	\$ 393.10	\$ 393.10	✓
Rear Knuckle Arm (LH) <i>distorsi</i> 386.90	1	\$ 538.10	\$ 538.10	✓
15577.40 SUB TOTAL			\$ 29,746.22	
12461.92 LESS 20%			\$ 5,949.24	
DISCOUNTED TOTAL			\$ 23,796.98	
Emblem-Blue Drive (LH) <i>hec</i> <i>SH</i> <i>Left SN</i>	1	\$ 26.60	\$ 26.60	✓
Front Door Comfort Logo (LH) <i>hec</i> SN	1	\$ 75.00	\$ 75.00	✓
Rear Door Tel No.Sticker(LH) <i>hec</i> SN	1	\$ 10.00	\$ 10.00	✓
Rear Door Comfortdelgro & Apps Sticker(LH) <i>hec</i> SN	1	\$ 80.00	\$ 80.00	✓
Front Tyre(LH) <i>sv</i> SN	1	\$ 216.00	\$ 216.00	X
Rear Tyre(LH) <i>sv</i> SN	1	\$ 216.00	\$ 216.00	X
191.60 SUB TOTAL			\$ 623.60	
Labour Charge				
Panel Beating	1	\$1,400.00	\$1,400.00	900/-
Spray Painting Charge	1	\$1,200.00	\$1,200.00	1000/-
Wiring Charge	1	\$120.00	\$120.00	30/-
Tuff Kote	1	\$160.00	\$160.00	40/-
Towing Charge	1	\$80.00	\$80.00	44
Remove/Refix Cushion & Upholstery Rear	1	\$150.00	\$150.00	80/-
Remove/Refix Undercarriage (RR)	1	\$400.00	\$400.00	150/-
Re-set Rear ABS System	1	\$400.00	\$400.00	44
Transfer of Door Mechanism FRONT	1	\$80.00	\$80.00	60/-
Re-set Frt Power Window System	1	\$200.00	\$200.00	44
Transfer of Door Mechanism REAR	1	\$80.00	\$80.00	60/-
Re-set Rear Power Window System 2680.00	1	\$200.00	\$200.00	44
Four Wheel Alignment	1	\$120.00	\$120.00	60/-
Remove/Refix Undercarriage (Frt)	1	\$400.00	\$400.00	150/-
Re-set Frt ABS System	1	\$200.00	\$200.00	44
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	150/-
TOTAL LABOUR			\$5,740.00	
ESTIMATE TOTAL			\$ 30,160.58	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance				

07/01/2021 @ 1700hr

HA Antura

Put by Put.

7/15,333.52

9 days.

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: