



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Jonathan Teh Yi Hui
	Reg No/Reg Date	SLW9178Z / 09/03/201
	Date In/Mileage	07/01/2021/ 0
	Chassis No	KNAPH81BMJ5417812
	Engine No	D4HBHH350558
	Make/Model	KIA/SORENTO 2.2 A SR GDCO
	Colour/Trim	MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	07/01/2021/ 09:50	QUK	282 / Kevin Leong	26897
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR TAILGATE, BUMPER & AFFECTED AREA REPAIR ON END PANEL					1600.00
E PNT98000 PAINT WORK ON REAR TAILGATE, REAR BUMPER & END PANEL					1050.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST					120.00
E PNT88000 REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR					120.00
E PNT88000 TO TRANSFER REAR BOOT ATTACHMENT TO NEW PANEL					120.00
M SUNDRY PERFORM RUST PREVENTION					80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM					30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					120.00
M SUNDRY TO SUPPLY C & C EMBLEM					50.00
M SUNDRY SUNDRIES					50.00
M PANEL ASSY-TAIL GATE		1.00	1445.00	20.00	1156.00
M PANEL ASSY-BACK		1.00	526.00	20.00	420.80
M TRIM ASSY-RR TRANSVERSE		1.00	59.00	20.00	47.20
M W/STRIP-TAIL GATE OPNG		1.00	128.00	20.00	102.40
M GLASS ASSY-TAIL GATE		1.00	690.00	20.00	552.00
M LOGO ASSY-KIA SUB		1.00	69.00	20.00	55.20
M EMBLEM-ECO DYNAMICS		1.00	37.00	20.00	29.60
M COVER-RR BUMPER,UPR		1.00	605.00	20.00	484.00
M WIRING HARNESS-R.P.A.S		1.00	240.00	20.00	192.00
M RAIL ASSY-REAR BUMPER		1.00	341.00	20.00	272.80
M ANTENNA ASSY-SMARTKEY		1.00	53.00	20.00	42.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Jonathan Teh Yi Hui
	Reg No/Reg Date	SLW9178Z / 09/03/201
	Date In/Mileage	07/01/2021/ 0
	Chassis No	KNAPH81BMJ5417812
	Engine No	D4HBHH350558
	Make/Model	KIA/SORENTO 2.2 A SR GDCO
	Colour/Trim	MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	07/01/2021/ 09:50	QUK	282 / Kevin Leong	26897		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	COVER-BLANKING RR FOG,LH			1.00	11.00	20.00	8.80
M	COVER-RR BUMPER LWR			1.00	565.00	20.00	452.00
M	SKID PLATE-RR BUMPER			1.00	103.00	20.00	82.40
M	COVER ASSY-RR BPR UNDER			1.00	30.00	20.00	24.00
M	RETAINER-BUMPER MTG			2.00	2.00	20.00	3.20
M	BRACKET ASSY-RR BUMPER SIDE,LH			1.00	25.00	20.00	20.00
M	BRACKET ASSY-RR BUMPER SIDE,RH			1.00	25.00	20.00	20.00
M	ULTRASONIC SENSOR-S.P.A.S			1.00	187.00	20.00	149.60
M	ULTRASONIC SENSOR-S.P.A.S			1.00	187.00	20.00	149.60

Estimate

Estimate

Confirm & accepted by

7% GST on	Nett 7604.00	7,604.00
		532.28
Total Payable		8,136.28

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.