

① IN LKK



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : Z/20/VC00/106952
Accident Date : 03-Jan-2021

No. : 31610

Date : 07-Jan-2021

Our Ref : 020639 / SANDRA

PAGE : 1

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
Singapore 199555

Not Authorized
1 Day &
Repair After Paint
16 days *Ex @ 600k*

ESTIMATED COST OF REPAIR FOR MIT FB70BB1SRDEA(2977cc)(2010) GBB9603S

1 pc	n/s front door			<i>Br</i>	950.00	c	✓
1 pc	n/s front door outer arch garnish			<i>Br</i>	150.00	c	✓
2 pcs	n/s front door hinges (top/ lower)	@ S\$120.00		<i>Bj</i>	240.00	c	✓
1 pc	n/s front door checker			<i>Bj</i>	115.00	c	✓
1 pc	n/s front door step garnish			<i>CM</i>	240.00	c	✓
1 pc	n/s front door weatherstrip			<i>CM</i>	140.00	c	✓
1 pc	n/s front door frame weatherstrip			<i>Br</i>	130.00	c	✓
1 pc	n/s front door glass			<i>Br</i>	165.00	c	✓
1 pc	n/s front door glass channel			<i>Di</i>	190.00	c	✓
1 pc	n/s front door glass railing			<i>Di</i>	80.00	c	✓
1 pc	n/s front door regulator and motor			<i>Bj</i>	540.00	c	✓
1 pc	n/s front door outer moulding			<i>Buc</i>	80.00	c	✓
1 pc	n/s front door outer vertical garnish - front			<i>Di</i>	100.00	c	✓
1 pc	n/s front door lock			<i>Ta</i>	265.00	c	✓
1 pc	n/s front door lock catch			<i>nd</i>	45.00	c	✓
1 pc	n/s front door lock switch			<i>CM</i>	65.00	c	✓
1 pc	n/s front door outer pull handle			<i>Di</i>	80.00	c	✓
1 pc	n/s front door inner trim- board			<i>CM</i>	580.00	c	✓
1 pc	n/s front door inner pull handle			<i>Di</i>	120.00	c	✓

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : Z/20/VC00/106952
Our Ref : 020639

Page : 2
No. : 31610

1 pc	n/s front door inner handle railing	D.S	180.00	c	✓
1 pc	n/s front door power window control panel	mg cm	360.00	c	✓
1 pc	n/s front door outer vertical garnish - rear	mg	55.00	c	✓
1 pc	n/s door 'A' pillar	R	1,050.00	c	✓
1 pc	n/s door 'A' pillar inner	R	950.00	c	✓
1 pc	n/s wingmirror - big	CM	80.00	c	✓
1 pc	n/s wingmirror - round	mg	60.00	c	✓
1 pc	n/s wingmirror - stay	R	180.00	c	✓
1 pc	n/s wingmirror stay cap cover	mg	35.00	c	✓
1 pc	n/s wingmirror stay inner cover	mg	55.00	c	✓
1 pc	front wiper panel garnish-big	way	175.00	c	✓
1 pc	n/s front wiper panel garnish -small	mg	45.00	c	✓
1 pc	front panel	R	1,000.00	c	✓
1 pc	n/s front corner panel	R	240.00	c	✓
2 pcs	headlamp (LH & RH)	mg cm @ S\$	340.00	c	✓
2 pcs	headlamp lower rubber lid (LH & RH)	mg cm @ S\$	9.50	c	✓
2 pcs	front side reflector (LH&RH)	mg cm @ S\$	65.00	c	✓
2 pcs	front signal lamp (LH & RH)	mg cm @ S\$	130.00	c	✓
1 pc	front windscreen glass	shotgun	480.00	c	✓
1 pc	front windscreen glass rubber	mg	195.00	c	✓
1 pc	n/s front windscreen pillar inner garnish	CM	195.00	c	✓
1 pc	wiper washer tank and motor		145.00	c	?
1 pc	n/s front windscreen pillar inner handle	mg	140.00	c	x
1 pc	o/s front door	R	950.00	c	x
1 pc	o/s front door lock	R	265.00	c	x
1 pc	roof top panel reinforcement-front	R	600.00	c	✓
1 pc	roof top trim lining	Mc form	1,200.00	c	✓
1 pc	dashboard assy	Bril cm	1,550.00	c	✓

Con't Page 3 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : Z/20/VC00/106952
Our Ref : 020639

Page : 3
No. : 31610

1 pc	dashboard reinforcement		195.00	c	?
1 pc	n/s dashboard glove compartment		260.00	c	✓
1 pc	dashboard centre console		380.00	c	✓
1 pc	dashboard air con control panel		1,800.00	c	?
1 pc	dashboard meter		2,400.00	c	?
1 pc	o/s dashboard meter console		260.00	c	✓
1 pc	o/s dashboard side garnish		125.00	c	✓
4 pcs	dashboard air con lourves	@ S\$ 85.00	340.00	c	?
4 pcs	dashboard air con lourves inner duct	@ S\$100.00	400.00	c	?
1 pc	dashboard inner fuses & relay box		480.00	c	?
1 pc	n/s dashboard lower garnish		165.00	c	✓
1 pc	front hand gear lever cover		265.00	c	?
2 pcs	front wiper blade (LH & RH)	@ S\$ 95.00	190.00	c	x
1 pc	air con blower		1,650.00	c	?
	air con cooling coil				
	air con heater unit				
1 pc	air con discharge pipe		340.00	c	?
1 pc	air con suction pipe		340.00	c	?
1 pc	radiator		1,250.00	c	?
1 pc	radiator fan cowling		165.00	c	?
1 pc	radiator fan blade		140.00	c	?
1 pc	radiator fan clutch		340.00	c	?
2 pcs	engine mounting (LH & RH)	@ S\$130.00	260.00	c	?
1 pc	gearbox mounting		110.00	c	?
			27,404.00		
			Add 15% :	4,110.60	
				31,514.60	
1 pc	n/s front door ROC sticker		15.00	sn	✓
1 pc	n/s front door inner speaker		120.00	sn	?
1 pc	front panel heat insulation		150.00	sn	?
1 pc	ERP bracket		26.00	sn	✓

Con't Page 4 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : Z/20/VC00/106952
Our Ref : 020639

Page : 4
No. : 31610

1 pc o/s front door ROC sticker
1 pc dashboard radio headset

na 15.00 sn X
240.00 sn 7

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

2,400.00 2000

To remove and renew front wind-
screen glass and conduct water
leak test.

100.00 601

To remove aircon condenser, pipes
and driers. Vaccum and recharge gas

100.00 ✓

To remove door's fittings

160.00 601

To conduct front wheel alignment
test.

na 80.00 X

To remove and renew front
instrument panel assy, to rewiring
and transfer instrument fittings.

280.00 220

To putty and respray on affected
portions.

1,400.00 1200

To focus headlamps. To check front
wiring and lighting operation.

50.00 201

Total : S\$36,650.60
=====

Singapore Dollars Thirty Six Thousand Six Hundred
and Fifty and Cents Sixty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.