

(1N) LKK

K. Kim Hin AUTO PTE LTD

CO. REG. NO: 199402370D
GST NO: M2-0123250-3

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 31610

Your Reference : Z/20/VC00/106952
Accident Date : 03-Jan-2021

Date : 07-Jan-2021

ur Ref : 020639 / SANDRA

PAGE : 1

ONPAC INSURANCE BHD
00 BEACH ROAD
17-04/07 THE CONCOURSE
Singapore 199555

*Not Withheld
1/18/2021 @ 13,000hr
Penny After Paint
16 days Ex @ 600hr*

ESTIMATED COST OF REPAIR FOR MIT FB70BB1SRDEA(2977cc)(2010) GBB9603S

pc	n/s front door	Bu	950.00	c	✓
pc	n/s front door outer arch garnish	Bu	150.00	c	✓
pcs	n/s front door hinges (top/ lower)	Bu	240.00	c	✓
pc	n/s front door checker	Bu	115.00	c	✓
pc	n/s front door step garnish	CM	240.00	c	✓
pc	n/s front door weatherstrip	CM	140.00	c	✓
pc	n/s front door frame weatherstrip	Bu	130.00	c	✓
pc	n/s front door glass	Bu	165.00	c	✓
pc	n/s front door glass channel	D's	190.00	c	✓
pc	n/s front door glass railing	D's	80.00	c	✓
pc	n/s front door regulator and motor	Bu	540.00	c	✓
pc	n/s front door outer moulding	Buc	80.00	c	✓
pc	n/s front door outer vertical garnish - front	Mi's	100.00	c	✓
pc	n/s front door lock	Tu	265.00	c	✓
pc	n/s front door lock catch	nd	45.00	c	✓
pc	n/s front door lock switch	CM	65.00	c	✓
pc	n/s front door outer pull handle	D's	80.00	c	✓
pc	n/s front door inner trim- board	CM	580.00	c	✓
pc	n/s front door inner pull handle	D's	120.00	c	✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Con't Page 2 ...

Con't Page 3 ...



Gigabit
Ethernet

Con't Page 4 . . .

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : 2/20/VC00/106952
Our Ref : 020639

Page : 4
No. : 31610

1 pc o/s front door ROC sticker
1 pc dashboard radio headset

nn 15.00 sn X
sn 240.00 sn X

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

2,400.00 2000

To remove and renew front wind-
screen glass and conduct water
leak test.

100.00 601

To remove aircon condenser, pipes
and driers. Vaccum and recharge gas

100.00 ✓

To remove door's fittings

160.00 601

To conduct front wheel alignment
test.

nn 80.00 X

To remove and renew front
instrument panel assy, to rewiring
and transfer instrument fittings.

280.00 2201

To putty and respray on affected
portions.

1,400.00 12001

To focus headlamps. To check front
wiring and lighting operation.

50.00 201

Total : S\$36,650.60
=====

Singapore Dollars Thirty Six Thousand Six Hundred
and Fifty and Cents Sixty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.