

PARTS COST FOR HONDA JAZZ. SMG4698U

Bonnet	\$ 548.00	bt ✓
Bonnet Lock	\$ 100.00	bt ✓
Support Panel	\$ 485.60	bt ✓
Support Top Garnish	\$ 85.00	X un ✓
Front Bumper	\$ 523.00	de ✓
Front Bumper spoiler	\$ 160.00	X un ✓
Front bumper centre lower grille	\$ 260.00	de ✓
Bumper sponge	\$ 70.00	X un ✓
Reinforcement	\$ 245.00	bt ✓
Front air duct	\$ 75.00	X nn ✓
Brace Panel	\$ 70.00	bt ✓
Headlights x 2. (HID)	\$ 1,250.00	car ✓
Wiper Tank	\$ 210.00	de ✓
Coolant tank	\$ 180.00	X un ✓
Radiator	\$ 750.00	bt ✓
Radiator Cowling	\$ 80.00	an ✓
Radiator spare tank	\$ 280.00	X un ✓
Coolant cap	\$ 25.00	ne ✓
Bumper clip x 20	\$ 80.00	30 ne ✓
Air con fan x 2	\$ 130.00	car ✓
Aircon condenser	\$ 660.00	bt ✓
Condenser Cowling	\$ 80.00	car ✓
Aircon Pipe x 2	\$ 160.00	bt ✓
Fender (RH)	\$ 330.00	bt ✓
Bonnet absorber x 2	\$ 440.00	X ✓
Stabiliser Link front LH & RH	\$ 170.00	X ✓
Lower arm LH & RH	\$ 180.00	X } un ✓
Bush	\$ 40.00	X } un ✓
Absorber LH & RH	\$ 520.00	X } un ✓
Tie Rod end	\$ 120.00	X ✓
Number plate	\$ 55.00	4 5 mis ✓
Front grille	\$ 237.00	car ✓
Front grille emblem	\$ 56.00	un ✓
Front fog lamp RH	\$ 180.00	car ✓
Front fog lamp RH garnish	\$ 55.00	mis ✓
Horn	\$ 30.00	car ✓
Bonnet insulator	\$ 120.00	de ✓

6659.60

w/ 5327.68

Total parts	\$ 8,361.60
-------------	-------------

LABOUR

Repair and fix/replace accident damaged parts	\$ 1,600.00 ⁷⁰⁰
To check wiring system & focus headlamps	\$ 280.00 ³⁰
To spray anti rust on accident affected areas	\$ 120.00 ³⁰
To putty and spray paint on all accident areas	\$ 1,200.00 ⁸⁰⁰
Wheel alignment & balancing	\$ 100.00 ^{un}
Top up aircon gas	\$ 120.00 ¹⁰⁰

Total Labour	\$ 3,300.00
--------------	-------------

TOTAL PARTS & LABOUR	\$ 10,360.00
----------------------	--------------

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5327.68

1660

6987.68

4/545200

07 days
9