

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21000311/UVD3E2

Date: 05/03/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00005692000
Claimant Vehicle No: FX28Z Insured Vehicle No: SLK9891K
Date of Loss: 18/12/2020 Nature of Claim: TP Claim No: SNM21D200101/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FX28Z**
Make & Model: KTM 1290 ADVENTURE, 1.3 Engine No: 0661400275
Reg. Date: 21/07/2016 (Man. Year: 2016) Chassis No: VBKV69401GM945298
Colour: Orange/Silver Odometer: 25841 km
Engine Capacity: 1301 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70Z R17 Rear Tyre Size: 190/55Z R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,692.00	2,892.60	799.40	21.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	280.00	220.00	60.00	21.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,972.00	3,112.60	859.40	21.64
Approved Total (Overridden) (S\$)		2,650.00		
Nett Amount (S\$)	3,972.00	2,650.00	1,322.00	33.28

INSPECTION

Date of Assignment: 07/01/2021
Date Inspected: 13/01/2021 Inspected At: Dirt Wheel Motor Trading (HQ)
Singapore 528838
Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Mar 2021)	
Parts:	N/A	KTM 1290 ADVENTURE 1.3 (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FX28Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CLUTCH LEVER	Scratched	159.00 F	*159.00 FL
2	1		*BALANCER	Scratched	58.00 F	*58.00 FL
3	1		*MIRROR (L)	Scratched	177.00 F	*177.00 FL
4	1		*TANK SPOILER (L)	Cut	707.00 F	*707.00 FL
5	1		*TANK SPOILER (R)	Cracked	707.00 F	*707.00 FL
6	1		*CRASH BAR	Cut	660.00 F	*660.00 FL
7	1		*GEAR SHIFTER	Bent	228.00 F	*228.00 FL
8	1		*FOOTREST FRONT (L)	Cut	133.00 F	*133.00 FL
9	1		*FOOTREST REAR (L)	Serviceable	133.00 F	*- FL
10	1		*FOOTREST BRACKET / REAR / (L)	Cut	284.00 F	*284.00 FL
11	1		*FOOTREST PLATE / (R)	Serviceable	13.00 F	*- FL
12	1		*SIDE STAND	Serviceable	332.00 F	*- FL
13	1		*KTM 3D STICKER	Necessary	39.00 F	*39.00 FL
14	1		*TANK SPOILER / LOWER GARNISH / (L)	Grazed	62.00 F	*62.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,692.00	3,214.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	321.40
Total Parts (\$\$)	3,692.00	2,892.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	280.00	220.00
Gross Labour Cost (\$\$)			280.00	220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >