

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21000318/GPA3Q2

Date: 19/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070012305

Claimant
Vehicle No : SKB5655L **Insured Vehicle No :** SKT4380R

Date of Loss: 19/12/2020 Nature of Claim: TP Claim No: 5927536907SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB5655L		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK034122
Reg. Date:	31/05/2017 (Man. Year: 2017)	Chassis No:	WAUZZZF52HA032374
Colour:	Grey	Odometer:	79211 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/30Z R20	Rear Tyre Size:	275/30Z R20
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,450.00	800.00	650.00	44.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	50.00	50.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,500.00	850.00	650.00	43.33
+ GST 7.00/7.00% (\$\$)	105.00	59.50	45.50	43.33
Nett Amount (\$\$)	1,605.00	909.50	695.50	43.33
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 07/01/2021

Date Inspected: 12/01/2021 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Ubi)
320 UBI ROAD 3
Singapore 408649

Estimated Period of Repair: 1.0 days

Adjuster: XING GUO QIANG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPORT RIM	Cut	1,450.00 FS	*800.00 FS
					Total Parts (\$\$)	800.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REINSTALL AND REPLACE SPORT RIM FRT	New	50.00	50.00
Gross Labour Cost (\$\$)			50.00	50.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >