

ComfortDelGro Engineering

## 320 UBI ROAD 3 SINGAPORE 408649 <u>ACCIDENT REPAIR ESTIMATES</u>

Our Ref:						
Type of Claim :		TP		Ve	ehicle No.	SKB5655L
Type of Claim				– Ma	ake & Model	: AUDI A5
				Ye	ear of Manufacture	: <b>2017</b>
				Ch	nassis No.	: WAUZZZF52HA032374
Ins Company :		AIG	1	En	gine No.	274920307444899
Excess :				_ Po!	licy No.	:
Date of Accident :	19	9.12.20	020	_ Tim	ne of Accident	:
Suggested Days of Re	epair : _			<u>In-</u> ł	house Vehicle Asse	essor
Repair Estimate	es			Cas	se Owner	:
Parts (a) Cost / List P	Price Items			Sign	nature	:
	1100			Cor	ntact No	
Plus/Less _				- 684	185 <del>725/26 JOHAR</del>	H/TINIE
Total of Cos	st / List			=	LKK Auto Cons the Repairer of	sultants hence notify f the following:
(b) Nett Price Ite	ems	_\$_		-	<ul><li>To resurvey befo</li><li>To display damage</li></ul>	ore/after spray painting ged part(s) during resurvey
Less _				-	<ul> <li>Parts prices are s</li> </ul>	subject to confirmation by is on a "Without Prejudice" basis
Total of Nett	. Item			=	<ul> <li>No illegal modific</li> </ul>	
(c) Special Nett	Items	\$	1,450.00	800	is subject to final	approval from Insurance Company
Total Parts Cost (App	endix A)	\$	1,450.00	_	Acknowledged by F Signature:	Repairer
Labour (Appendix B)		\$	50.00	05	Date:	
Total Repair Cost		\$	1,500.00	850		
The above total will be	subjected to	o 7% (	G.S.T.	que	, Qiang 6	9 lkkausto. Con - 82880282
Name of Surveyor		:	6	wo C	Ziang	- 82880282
Company		:		KK,		
Survey conducted or	n	:	12	<del>///</del>	<del>2 √</del> ay —	
Remarks By Surveyo	<u>or</u>		A.	Her	repair 1	Notes.
(a) The repair of this	vehicle is a	uthori	ized / is not	authorized (	until further notice.	
(b) Recommended D	ays of Repa	air :	:	1	_ day(s)	
(c) Resurvey		:	Required /	Not Require	ed	
(d) Excess		:\$_				
(e) Signature of surve	eyor	:			Date: _	

Spark Car Care
ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649 Tel: 68438723/68438736 FAX: 67436072

	-h	_		_
L	1U	0	u	ı

Vehicle No. :	SKB5655L	Case Owner	:	:		
Make & Model:	AUDI A5	Year of Manufacture	:	2016		

Wake	& Model : AUDI A5 Year of Manufacture		2010
S/No	Labour Description	Esimated Price	Adjusted Price
1	TO REMOVE & REINSTALL AND REPLACE SPORT RIM FRT	\$50.00	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

## ComfortDelGro Engineering Pte Ltd 320 UBI ROAD 3 SINGAPORE 408649

TEL :68438723/68438736 Fax:67436072

## e Parts

ehicle No	: <u>SKB5655L</u>	Case Owner : <b>JOHARI</b>
Make & Model	: AUDI A5	Year Manufacture : <b>2017</b>
Chassis No	:	Engine No :
Sales Order	:	Supplier :
Order By	:	Type of Claim

S/No	Part Description	QTY	Cost	List	Nett		Disposition By
1	SPORTRIM / Cut.		Price	Price	Price	S/N	Surveyor
2	7 0001	1			/	\$1450.00	
3				COMFO	RTDELGRO F	14 CHIAPTIMAC	PTE LTO
4					3Z0 (/SI	FIE 4000 10	
5					11	1000,0	
6							
7							
8							
9						-	
10							
11							-
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							-
26					+	-	
27					-		
28							
9		<del>-      </del>					
0							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.