

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

QBE Insurance (Singapore) Pte Ltd

Blk 60 , Anson Road # 11 - 01
 Maple Tree Anson
 Singapore 179914
 Tel : 6224 - 6633
 Fax : 6534 - 5356

Quotation

DATE : 04.01.2021
 VEH NO : SJY5912K
 MODEL : Merc C200
 D O A : 29.12.2020
 YR REF : GBF4176U

Cecilia

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJY5912K (MERCEDES C200)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Number Plate Garnish <i>cracked</i>	1	75.00 ✓
2	Front Bumper <i>Distorted</i>	1	1,251.00 ✓
3	Front Bumper Side Holder <i>Deformed</i>	2	96.00 ✓
4	Front Bumper Lower Grille <i>Deformed</i>	1	135.00 ✓
5	Front Bumper Sensor <i>3 pieces damaged</i>	6	1,440.00 <i>720</i>
6	Front Bumper Sensor Wire Harness <i>snapped</i>	1	295.00 ✓
7	Front Bumper Fpg Lamp <i>RH cracked</i>	2	644.00 <i>322</i>
8	Front Bumper Fog Lamp Cover <i>RH Distorted</i>	2	284.00 <i>142</i>
9	Front Bumper Fog Lamp Cover Chrome Moulding <i>RH Distorted</i>	2	206.00 <i>103</i>
10	Front Bumper Sponge <i>cracked</i>	1	183.00 ✓
11	Front Bumper Reinforcement <i>Best</i>	1	455.00 ✓
12	Front Bumper Reinforcement Bracket <i>RH Bent</i>	2	554.00 <i>277</i>
13	Front Bumper Undercover <i>torn</i>	1	356.00 ✓
14	Front Bumper Lower Chrome Moulding <i>new</i>	2	176.00 ✓
15	Front Bumper Inner Frame <i>3 Distorted</i>	1	199.00 ✓
16	Front Bumper Inner Beam <i>Distorted</i>	1	159.00 ✓
17	Front Bumper Tow Cover <i>Distorted</i>	1	36.00 ✓
18	Front Grille <i>Smashed</i>	1	695.00 ✓
19	Front Grille Logo <i>new</i>	1	132.00 ✓
20	Head Lamp <i>RH Smashed, LH cracked</i>	2	2,340.00 ✓
21	Head Lamp ECU <i>Not new</i>	2	762.00 <i>X</i>
22	Head Lamp Bracket <i>RH Distorted</i>	2	210.00 <i>105</i>
23	Head Lamp Top Panel <i>Distorted</i>	2	430.00 ✓
24	Bonnet <i>Distorted</i>	1	1,720.00 ✓
25	Bonnet Lock <i>Jammed</i>	1	376.00 ✓
26	Bonnet Lock Catch <i>Best</i>	2	130.00 ✓
27	Bonnet Lock Cable <i>Jammed</i>	1	49.00 ✓
28	Bonnet Lock Striker <i>new</i>	1	69.00 ✓
29	Bonnet Stopper <i>Missing</i>	2	58.00 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR SJY5912K (MERCEDES C200)

30	Bonnet Insulator	<i>crumpled</i>	1	235.00	✓
31	Bonnet Weatherstripe	<i>ut</i>	1	78.00	✓
32	Bonnet Logo	<i>Nu</i>	1	58.00	✓
33	Bonnet Hinges	<i>Bent</i>	2	220.00	✓
34	Bonnet Damper	<i>Damaged</i>	2	370.00	✓
35	Front Support Panel	<i>Distorted</i>	1	765.00	✓
36	Front Support Panel Top Cover	<i>Distorted</i>	1	225.00	✓
37	Front Support Panel Bracket	<i>Bent</i>	1	59.00	✓
38	Horn	<i>crushed</i>	2	270.00	✓
39	Horn Bracket	<i>Bent</i>	2	90.00	✓
40	Engine Top Cover	<i>crushed</i>	1	389.00	✓
41	Air Con Condenser	<i>Distorted</i>	1	1,165.00	✓
42	Air Con Liquid Pipe	<i>3 new</i>	1	281.00	x
43	Air Con Suction Pipe		1	361.00	x
44	Air Con Discharge Pipe		1	384.00	x
45	Radiator	<i>Distorted</i>	1	1,185.00	✓
46	Radiator Top Hose	<i>torn</i>	1	78.00	✓
47	Radiator Lower Hose	<i>new</i>	1	72.00	x
48	Radiator Mounting	<i>new</i>	2	50.00	✓
49	Radiator Fan Assy	<i>crushed</i>	1	945.00	✓
50	Radiator Spare Tank	<i>3 new</i>	1	195.00	x
51	Radiator Spare Tank Hose		1	32.00	x
52	Intercooler	<i>Distorted</i>	1	1,105.00	✓
53	Intercooler Cover	<i>crushed</i>	1	75.00	✓
54	Oil Cooler Pipe	<i>Bent</i>	1	189.00	✓
55	Air Duct	<i>Distorted</i>	1	135.00	✓
56	Engine Mounting - Front	<i>3 torn</i>	1	249.00	✓
57	Engine Mounting - Rear	<i>RH torn</i>	1	217.00	✓
58	Side Engine Mounting		2	590.00	295
59	Air Intake Hose	<i>Deformed</i>	1	241.00	✓
60	Front Fender - LH & RH	<i>RH Distorted</i>	2	1,746.00	873
61	Front Fender Bracket - RH	<i>Bent</i>	1	48.00	✓
62	Front Fender Inner Cowling - RH (Front)	<i>3 torn</i>	1	125.00	✓
63	Front Fender Inner Cowling - RH (Rear)		1	119.00	✓
64	Front Fender Inner Top Panel - RH	<i>crushed</i>	1	298.00	✓
65	Front Windscreen	<i>crushed</i>	1	942.00	✓
66	Front Windscreen Moulding	<i>new</i>	1	155.00	✓
67	Front Driver Seat Belt	<i>3 Activated</i>	1	732.00	✓
68	Front Passenger Seat Belt		1	1,245.00	✓
69	Steering Air Bag	<i>3 Activated</i>	1	189.00	✓
70	Steering Air Bag Sensor		1	2,694.00	✓
71	Dashboard	<i>torn</i>	1	2,541.00	✓
72	Dashboard Air Bag	<i>3 Activated</i>	1	189.00	✓
73	Dashboard Air Bag Sensor		1	1,026.00	✓
74	Air Bag ECU	<i>Activated</i>	1	1,050.00	✓
75	Front Wheel Rim - RH	<i>ut</i>	1	1,230.00	615
76	Front Shock Absorber	<i>RH Bent</i>	2		

RE: **ESTIMATE FOR ACCIDENT REPAIR SJY5912K (MERCEDES C200)**

77	Front Lower Arm	2
78	Front Control Arm	2
79	Front Knuckle Arm	2
80	Front Wheel Hub C/w Bearing	2
81	Front Anti Roll Bar	1
82	Front Anti Roll Bar Linkage	2
83	Front Sub Frame	1
84	Steering Rack & Pinion	1

Less 10%

780.00	380
650.00	325
1,550.00	775
910.00	455
315.00	x
170.00	✓
1,490.00	✓
5,051.00	x

\$	49,800.00
	(4,980.00)
	44,820.00

S/NETT ITEMS

1	Front Number Plate	1
2	Front Number Plate Holder	1
3	Front Bumper Clips	1 set
4	Front Bumper Undercover Clips	1 set
5	Front Grille Clips	1 set
6	Bonnet Insulator Clips	1 set
7	Bonnet Weatherstripe Clips	1 set
8	Front Fender Inner Cowling Clips - RH	1 set
9	Front Windscreen Sealant	1 set
10	Front Windscreen Solar Film	1
11	ERP Bracket	1
12	Front Tyre - RH	1
13	Coolant	1

Total parts

30.00	✓
30.00	✓
50.00	✓
30.00	✓
30.00	✓
50.00	30
20.00	✓
30.00	✓
60.00	✓
280.00	200
23.00	✓
350.00	x
60.00	✓

1,043.00

\$ 45,863.00

LABOUR CHARGE

- To knocking & pull out front portion & renew above parts
- To putty & spray up paint works
- To check wiring system
- To remove front bumper sensor
- To spray tuff coat
- To remove condenser and to top up aircon gas
- To remove radiator and to top up coolant

\$	2,000.00	1800
\$	2,000.00	1300
\$	300.00	100
\$	150.00	80
\$	200.00	120
\$	120.00	80
\$	120.00	80

RE : ESTIMATE FOR ACCIDENT REPAIR SJY5912K (MERCEDES C200)

8	To remove engine and gearbox to facilitate repairs	\$	500.00 ✓
9	To remove front windscreen	\$	180.00 120
10	To remove dashboard	\$	350.00 250
11	To remove air bags and to reset air bag system	\$	600.00 500
12	To remove seat belts	\$	200.00 100
13	To perform diagnostic test	\$	200.00 100
14	To remove front undercarriage system	\$	650.00 450
15	To repair and straighten front chassis member	\$	400.00 280
16	Towing fees (king roller)	\$	120.00 ✓

Total Labour \$ **8,090.00**

Grand Total \$ **53,953.00**

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 39828.

h/s: 31.8K.

21 Days.