

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0015/2021/NS
DATE : 7-Jan-21
WIP : 10334

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR MUHAMMAD ZULKARNAIN BIN ABDUL RAHMAN
ADDRESS : 677D PUNGGOL DRIVE
#04-746
SINGAPORE 824677
TELEPHONE : HP +65 91797474
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900003597
VEHICLE NO : **SMH 1631 B**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 14/1/2019
ENGINE NO : CHZ C26002
CHASSIS NO : WAUZZZ8V2K1013151
MILEAGE : 49727KM
DATE IN : 6-Jan-21
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Jan-21
PLACE OF ACCIDENT : MOUNTBATTEN RD AND STADIUM BLVD JUNCTION

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMH 1631 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	
2	TO REMOVE AND REINSTALL AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	
3	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00	
SUB TOTAL LABOUR CHARGES		: \$ 6,730.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMH 1631 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND RHS FRONT FENDER.	\$ 3,200.00	
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: <u>\$ 10,402.00</u>	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 1631 B

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER	\$	1,987.00	
2 FRONT BUMPER FIXING PARTS	\$	187.00	
3 FRONT BUMPER GUIDE SECTION - RH	\$	39.00	
4 FRONT BUMPER GRILLE -CENTRE	\$	160.00	
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$	536.00	
6 FRONT BUMPER CLOSING ELEMENT - RH	\$	297.00	
7 FRONT BUMPER COVER TRIM - RH	\$	163.00	
8 WHEEL HOUSING LINER ADAPTER - RH	\$	38.00	
9 RADIATOR GRILLE	\$	1,406.00	
10 RADIATOR GRILLE CLOSING ELEMENT	\$	191.00	
11 FRONT BUMPER AIR GUIDE GRILLE - RH	\$	188.00	
12 FRONT REINFORCEMENT BEAM	\$	795.00	
13 FRONT BUMPER FOAM FILLER PIECE	\$	189.00	
14 FOAM FILLER PIECE COVER	\$	122.00	
15 SIGNAL HORN - RH LOW TONE	\$	200.00	
16 FRONT FENDER - RH	\$	851.00	
17 FRONT FENDER ATTACHMENT PARTS	\$	72.00	
18 FRONT FENDER BRACKET - RH	\$	39.00	
19 FRONT FENDER BRACE	\$	96.00	
20 WHEEL HOUSING LINER - RH	\$	169.00	
SUB TOTAL SPARE PARTS	:	\$ 7,725.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 1631 B

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 89.00	
22 BONNET		\$ 3,134.00	
23 BONNET ATTACHMENT PARTS		\$ 165.00	
24 BONNET LID HINGE - LH/RH	2	\$ 124.00	
25 BONNET CATCH HOOK		\$ 90.00	
26 BONNET STRIKER - RH		\$ 110.00	
27 BONNET EDGE PROTECTION		\$ 28.00	
28 BONNET LID LOCK		\$ 214.00	
29 LED HEADLIGHT - RH		\$ 5,455.00	
30 MAIN LIGHT ELECTRONICS POWER MODULE - RH		\$ 758.00	
31 LED WITH HEAT SINK - RH		\$ 733.00	
32 LIGHT CONTROL SYSTEM CONTROL UNIT		\$ 557.00	
33 HEADLIGHT HOSE - RH		\$ 40.00	
34 LIFT CYLINDER - RH		\$ 142.00	
35 LIFT CYLINDER HOSE - RH		\$ 68.00	
36 LOCK CARRIER		\$ 727.00	
37 TEMPERATURE SENSOR BRACKET		\$ 19.00	
38 RADIATOR AIR GUIDE - RH		\$ 25.00	
39 RADIATOR AIR GUIDE - UPPER CENTRE		\$ 12.00	
40 READY MIX COOLANT		\$ 179.00	
SUB TOTAL SPARE PARTS	:	\$ 12,669.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 1631 B

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
41 AIRCON STICKER	NEC	\$ 8.00	
42 CAUTION SIGN STICKER	NEC	\$ 14.00	
43 AIR INTAKE AIR GUIDE - LOWER		\$ 56.00	
44 AIR INTAKE AIR DUCT COVER		\$ 29.00	
45 AIR INTAKE AIR GUIDE - INNER		\$ 20.00	
46 AIR INTAKE WATER DRAINAGE HOSE		\$ 33.00	
47 AIR INTAKE AIR GUIDE HOSE		\$ 66.00	
48 FRONT ALUMINIUM RIM - RH		TBC	
49 FRONT NO PLATE	S/N	\$ 60.00	
50 SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS	:	\$ 20,980.00	
TOTAL LABOUR CHARGES	:	\$ 10,402.00	
GRAND TOTAL	:	\$ 31,382.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT