

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1041/2020/NS
DATE : 4-Jan-21
WIP : 65244

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : WAH SYN ENGINEERING PTE LTD
ADDRESS : 33 UBI AVE 3
#04-31/32
SINGAPORE 408868
TELEPHONE : OFF +65 67473785
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800098835-01
VEHICLE NO : **SMD 5435 X**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 24/8/2018
ENGINE NO : CHZ 922140
CHASSIS NO : WAUZZZ8V0J1062038
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Dec-21
PLACE OF ACCIDENT : BUKIT TIMAH ROAD

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMD 5435 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00	
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 5,202.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 5435 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER		\$ 1,987.00	
2 FRONT BUMPER FIXING PARTS		\$ 185.00	
3 FRONT BUMPER GUIDE SECTION - RH		\$ 38.00	
4 WHEEL HOUSING LINER ADAPTER - RH		\$ 37.00	
5 FRONT BUMPER CLOSING ELEMENT - RH		\$ 293.00	
6 FRONT BUMPER COVER TRIM - RH		\$ 161.00	
7 FRONT BUMPER AIR GUIDE GRILLE - RH		\$ 186.00	
8 FRONT FENDER - RH		\$ 841.00	
9 FRONT FENDER ATTACHMENT PARTS		\$ 71.00	
10 FRONT FENDER BRACKET - OUTER		\$ 38.00	
11 FRONT FENDER BRACKET - INNER		\$ 27.00	
12 FRONT FENDER BRACE		\$ 95.00	
13 WHEEL HOUSING LINER - RH		\$ 167.00	
14 WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 88.00	
15 LED HEADLIGHT - RH		\$ 5,455.00	
16 LIFT CYLINDER - RH		\$ 141.00	
17 FRONT ALUMINIUM RIM - RH		\$ 699.00	
18 SUNDRIES		\$ 250.00	
TOTAL SPARE PARTS	:	\$ 10,759.00	
TOTAL LABOUR CHARGES	:	\$ 5,202.00	
GRAND TOTAL	:	\$ 15,961.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT