



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1041/2020/NS
DATE : 04-Jan-21
WIP : 65244

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

5 days - ok - Jy - 26 Mar 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : WAH SYN ENGINEERING PTE LTD
ADDRESS : 33 UBI AVE 3
#04-31/32
SINGAPORE 408868
TELEPHONE : OFF +65 67473785
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800098835-01
VEHICLE NO : SMD 5435 X
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 24/08/2018
ENGINE NO : CHZ 922140
CHASSIS NO : WAUZZZ8V0J1062038
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Dec-20
PLACE OF ACCIDENT : BUKIT TIMAH ROAD



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMD 5435 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	\$ 250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	\$ 1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00	\$ 1,100.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	\$ 280.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 5,202.00	\$ 2,822.00



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMD 5435 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 FRONT BUMPER	\$	1,987.00	\$	1,589.60
2 FRONT BUMPER FIXING PARTS	\$	185.00		
3 FRONT BUMPER GUIDE SECTION - RH	\$	38.00		
4 WHEEL HOUSING LINER ADAPTER - RH	\$	37.00		
5 FRONT BUMPER CLOSING ELEMENT - RH	\$	293.00		
6 FRONT BUMPER COVER TRIM - RH	\$	161.00		
7 FRONT BUMPER AIR GUIDE GRILLE - RH	\$	186.00		
8 FRONT FENDER - RH	\$	841.00	\$	672.80
9 FRONT FENDER ATTACHMENT PARTS	\$	71.00		
10 FRONT FENDER BRACKET - OUTER	\$	38.00		
11 FRONT FENDER BRACKET - INNER	\$	27.00		
12 FRONT FENDER BRACE	\$	95.00	\$	75.68
13 WHEEL HOUSING LINER - RH	\$	167.00		
14 WHEEL HOUSING LINER ATTACHMENT PARTS	\$	88.00		
15 LED HEADLIGHT - RH	\$	5,455.00	\$	4,364.00
16 LIFT CYLINDER - RH	\$	141.00		
17 FRONT ALUMINIUM RIM - RH	\$	699.00	\$	558.80
18 SUNDRIES	\$	250.00	\$	20.24
TOTAL SPARE PARTS	:	\$ 10,759.00	\$	7,281.12
TOTAL LABOUR CHARGES	:	\$ 5,202.00	\$	2,822.00
GRAND TOTAL	:	\$ 15,961.00	\$	10,103.12

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-26/02/21