

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0018/2021/NS
DATE : 7-Jan-21
WIP : 10420

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR WIDDEK HELMUT
ADDRESS : 267 OCEAN DRIVE
SINGAPORE 098424
TELEPHONE : HP +65 91111300
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900141530
VEHICLE NO : **SFQ 1282 K**
MODEL CODE : AUDI A8 L D5 3.0 TFSI QU
MODEL YEAR : 13/8/2019
ENGINE NO : CZS 009717
CHASSIS NO : WAUZZZF87JN014090
MILEAGE : 8206KM
DATE IN : 6-Jan-21
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5-Jan-21
PLACE OF ACCIDENT : 16 SIMEI STREET 1 MELVILLE PARK CAR PARK



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFQ 1282 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR SPARE WHEEL HOUSING. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,800.00	
3	TO RESPRAY REAR UPPER BUMPER, REAR BUMPER LOWER SPOILER AND PSARE WHEEL HOUSING.	\$ 3,600.00	
4	TO REMOVE AND RENEW REAR SUSPENSION ASSEMBLY WITH SUBFRAME. INCLUDING REAR AXLE AND PORPELLOR SHAFT. RENEW ACCORDINGLY.	S/N \$ 2,800.00	
SUB TOTAL LABOUR CHARGES		: \$ 8,560.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SFQ 1282 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
5	TO REMOVE AND RENEW FUEL TANK ASSY.	S/N \$ 780.00	
6	TO RENEW BOTH REAR RIMS. TO CARRY OUT PRE AND POST WHEEL ALIGNMENT.	S/N \$ 560.00	
7	TO REMOVE AND RENEW BOTH REAR EXHAUST SILENCER AND ALIGN TO POSITION.	S/N \$ 480.00	
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 10,572.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFQ 1282 K

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 REAR ALUMINIUM RIM - LH/RH	2	\$ 2,862.00	
2 SUPPORT FRAME		\$ 3,454.00	
3 ECCENTRIC WASHER	2	\$ 11.00	
4 REAR SUBFRAME SUPPORT		\$ 154.00	
5 REAR AXLE DIFFERENTIAL		\$ 13,680.00	
6 AXLE OIL		\$ 133.00	
7 REAR DRIVE SHAFT - LH/RH	2	\$ 3,930.00	
8 GUARD PLATE - LH		\$ 132.00	
9 SEALANT		\$ 192.00	
10 LOWER ARM WISHBONE - LH/RH	2	\$ 1,718.00	
11 UPPER ARM WISHBONE - LH/RH	2	\$ 1,186.00	
12 LOWER WISHBONE STEEL VERSION - LH/RH	2	\$ 458.00	
13 REAR WISHBONE - LH/RH	2	\$ 590.00	
14 TRACK ROD - LH/RH REAR	2	\$ 394.00	
15 WHEEL BEARING HOUSING - LH/RH	2	\$ 1,964.00	
16 UPPER ARM WISHBONE STEEL VERSION STONE CHIP GUARD - LH/RH INNER	2	\$ 86.00	
17 UPPER ARM WISHBONE STONE CHIP GUARD - LH/RH	2	\$ 90.00	
18 REAR STEERING GEAR		\$ 5,991.00	
19 REAR SHOCK ABSORBER - LH/RH	2	\$ 9,198.00	
20 REAR SUSPENSION FORKS	2	\$ 527.00	
SUB TOTAL SPARE PARTS	:	\$ 46,750.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFQ 1282 K

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 ANTI-ROLL BAR		\$ 433.00	
22 COUPLING ROD - REAR	2	\$ 171.00	
23 CARDAN SHAFT		\$ 5,189.00	
24 REAR SILENCER - LH/RH	2	\$ 2,904.00	
25 REAR SILENCER DUAL CLIP	2	\$ 118.00	
26 CENTRE SILENCER		\$ 1,303.00	
27 CENTRE SILENCER DUAL CLIP	4	\$ 236.00	
28 EXHAUST SILENCER BRACKET	2	\$ 83.00	
29 UNDERBODY TRIM - REAR CENTRE		\$ 278.00	
30 UNDERBODY TRIM - LH/RH REAR	2	\$ 378.00	
31 REAR SILENCER HEAT SHIELD - LH/RH	2	\$ 310.00	
32 REAR SUBFRAME BRACE - LH/RH	2	\$ 1,038.00	
33 HEAT SHIELD - REAR		\$ 245.00	
34 FUEL TANK		\$ 6,972.00	
35 FUEL TANK SEAL RING		\$ 40.00	
36 FUEL TANK PROTECTIVE PLATE		\$ 79.00	
37 REAR BUMPER		\$ 3,976.00	
38 REAR BUMPER FIXING PARTS		\$ 164.00	
39 REAR BUMPER CLOSING ELEMENT - LH/RH	2	\$ 68.00	
40 REAR BUMPER SPOILER		\$ 1,114.00	
SUB TOTAL SPARE PARTS	:	\$ 25,099.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFQ 1282 K

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
41 REAR BUMPER SECURING STRIP		\$ 157.00	
42 REAR BUMPER TRIM - LH/RH LOWER	2	\$ 1,014.00	
43 REAR BUMPER CHROME TRIM - LOWER CENTRE		\$ 309.00	
44 REAR BUMPER CHROME TRIM - LH/RH UPPER	2	\$ 578.00	
45 REAR BUMPER CHROME TRIM - UPPER CENTRE		\$ 520.00	
46 REAR LIGHT REFLECTOR - LH/RH OUTER	2	\$ 82.00	
47 REAR LIGHT REFLECTOR - LH/RH INNER	2	\$ 60.00	
48 REAR PARKING AID SENSOR	2	\$ 484.00	
49 REAR PARKING AID SEAL RING	4	\$ 14.00	
50 REAR BUMPER CARRIER		\$ 1,525.00	
51 REAR BUMPER HOLDING STRAP		\$ 106.00	
52 REAR BUMPER SEAL - LH/RH	2	\$ 28.00	
53 STONE CHIP	S/N	\$ 180.00	
54 SUNDRIES		\$ 600.00	
TOTAL SPARE PARTS	:	\$ 77,506.00	
TOTAL LABOUR CHARGES	:	\$ 10,572.00	
GRAND TOTAL	:	\$ 88,078.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT