

 **PREMIUM AUTOMOBILES**

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0850/2020/NS
DATE : 9-Nov-20
WIP : 56796

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MDM LIM BEE TIN
ADDRESS : BLK 749 TAMPINES ST 44
#04-237
SINGAPORE 520479
TELEPHONE : HP +65 97874344
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100431262-05
VEHICLE NO : **SDW 23 R**
MODEL CODE : AUDI A4 1.8T FIS MU 8K203
MODEL YEAR : 30/9/2015
ENGINE NO : CJE 107520
CHASSIS NO : WAUZZZ8K8FA154642
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5-Nov-20
PLACE OF ACCIDENT : PAYA LEBAR ROAD OPPOSITE AQUEEN
HOTEL



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDW 23 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 280.00	✓
2	TO DISMANTLE AND RENEW LHS REAR DOOR. TO REPAIR LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,400.00	500
3	TO RESPRAY LHS REAR DOOR, DOOR HANDLE AND LHS REAR FENDER.	\$ 2,300.00	Door := 550 Handle := 100 <hr/> 650
4	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	x.
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>4,452.00</u>	



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDW 23 R

<u>S/N PARTS DESCRIPTION</u>	<u>QTY</u>	<u>DAMAGED PARTS & PRICES</u>		<u>REMARKS</u>
		<u>S/NETT</u>		
1 REAR DOOR - LH <i>Painted.</i>		\$	2,881.00	✓
2 REAR DOOR ATTACHMENT PARTS <i>New</i>		\$	83.00	X
3 REAR DOOR OUTER SEAL <i>Neu</i>	NEC	\$	220.00	✓
4 BONDING AGENT <i>?</i>	NEC	\$	47.00	?
5 CLEANING SOLUTION <i>?</i>	NEC	\$	65.00	?
6 REAR DOOR CATCH <i>?</i>		\$	119.00	?
7 WHEEL HOUSING LINER - LH <i>New</i>		\$	219.00	X.
8 WHEEL HOUSING LINER ATTACHMENT PARTS <i>New</i>		\$	44.00	X
9 REAR ALUMINIUM RIM - LH <i>New</i>		\$	1,256.00	X.
10 SUNDRIES <i>?</i>		\$	200.00	?
TOTAL SPARE PARTS	:	\$	5,134.00	
TOTAL LABOUR CHARGES	:	\$	4,452.00	
GRAND TOTAL	:	\$	9,586.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

 **PREMIUM AUTOMOBILES**

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME : *Adrian Lj*
SURVEYED DATE : *02/01/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT