



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1039/2020/NS
DATE : 2-Jan-21
WIP : 65100

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR ROOPAK SEKHRI
ADDRESS : 50 SIMS DRIVE
#06-148
SINGAPORE 380050
TELEPHONE : HP +65 98521897
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070172487
VEHICLE NO : **SBN 7541 L**
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR : 15/12/2020
ENGINE NO : CZD C09552
CHASSIS NO : WAUZZZF32M1023683
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Dec-21
PLACE OF ACCIDENT : THOMSON ROAD

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SBN 7541 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 280.00	X
2	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY.	S/N \$ 400.00	280.
3	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 280.00	X.
4	TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER AND LHS FRONT DOOR. TO RENEW LHS FRONT FENDER AND LHS FRONT DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00	250.
SUB TOTAL LABOUR CHARGES		: \$ 4,160.00	

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 9125 K**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND LHS FRONT DOOR. ✓	\$ 3,400.00 ✓	1100
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00 ✓	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 8,032.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBN 7541 L

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 FRONT SPOILER <i>Neu</i>		\$	379.00	<i>x</i>
2 FRONT BUMPER GUIDE SECTION - LH <i>Neu</i>		\$	38.00	<i>x</i>
3 FRONT FENDER - LH <i>Rejis</i>		\$	1,271.00	<i>x</i>
4 FRONT FENDER ATTACHMENT PARTS <i>Neu</i>		\$	62.00	<i>x</i>
5 FRONT FENDER BRACE - LH <i>Neu</i>		\$	87.00	<i>x</i>
6 FRONT FENDER BRACKET - LH <i>Neu</i>		\$	31.00	<i>x</i>
7 FRONT WHEEL COVER - LH/RH <i>LH cut</i>	2	\$	530.00	<i>265</i>
8 FRONT DOOR - LH <i>Rejis</i>		\$	2,542.00	<i>x</i>
9 FRONT DOOR OUTER SEAL - LH <i>Neu</i>	NEC	\$	164.00	<i>x</i>
10 FRONT DOOR ATTACHMENT PARTS <i>Neu</i>		\$	155.00	<i>x</i>
11 FRONT DOOR CATCH <i>Neu</i>		\$	119.00	<i>x</i>
12 FRONT DOOR COVER - LH <i>cut</i>		\$	265.00	<i>✓</i>
13 FRONT ALUMINIUM RIM - LH <i>Neu</i>		\$	756.00	<i>x</i>
14 SUNDRIES <i>?</i>		\$	250.00	<i>?</i>
TOTAL SPARE PARTS	:	\$	6,649.00	
TOTAL LABOUR CHARGES	:	\$	8,032.00	
GRAND TOTAL	:	\$	14,681.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King.
SURVEYED DATE : 07/01/21
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised , 04 days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT