



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/III20012511/Gtd3e2-1	
			Date: 18/03/2021	
			Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3032C	Veh. Inspected	SKR 5792P	
Policy No.	MCOM0015	Coverage (\$)	0.00	
Claim No.	MCT20110062	Excess (\$)	0.00	
Assign From		Assign Date	30/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA ODYSSEY 2.4	c.c	2356	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JHMRC1880EC204312	Colour	BLACK	
Odometer	97799 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/11/2020	Inspection Date	07/12/2020	
Survey held at	STAR AUTOMOBILE SERVICES BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-255 SINGAPORE 569536			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	