

# AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

601, Choa Chu Kang Street 62, # 04-07, Singapore 680601

E-mail Address: aasschee@singnet.com.sg

Tel: 96623655, 67655661

RCB No. 43037800M

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Registration No: **SKR 5792P**

Attachment to report no. TP/0049/12/2020

REPAIRER'S ESTIMATE		OUR RECOMMENDATIONS	
Replacement Of Damaged Panels/Parts and Labour Charges	S\$ Price	Conditions	S\$ Price
<b>REPLACEMENT OF DAMAGED PANELS/PARTS</b>		<b>LUMP SUM REPAIR</b>	<b>LESS 20%</b>
01. 1 pc rear bumper <i>X repair</i>	557.50	Grazed/Dented/Bent - Allowable	557.50
02. 1 pc rear bumper RH clamp kit	35.00	Serviceable - Not Allowed	0.00
03. 1 pc rear LH fender	969.00	Grazed/Dented - Not Allowed	To repair
04. 1 pc rear LH sliding door <i>X repair</i>	1,026.00	Grazed/Dented - Allowable	1,026.00
05. 1 pc rear LH door upper moulding	57.00	Serviceable - Not Allowed	0.00
06. 1 pc rear LH door lower protector /	321.90	Grazed/Dented - Allowable	321.90 ✓
07. 1 pc front LH door <i>X repair</i>	918.50	Grazed/Dented - Allowable	918.50
08. 1 pc front LH door upper moulding	38.00	Serviceable - Not Allowed	0.00
09. 1 pc front LH door lower protector /	326.40	Grazed/Dented - Allowable	326.40 ✓
10. 1 pc front LH door wingmirror assy <i>X repair</i>	630.00	Grazed - Allowable	630.00
11. 2 pcs LH wheel rim @ 938.70 <i>1pc / Cut</i>	1,877.40	Grazed/Dented - Allowable	1,877.40 ✓
	-----		-----
	6,756.70		5,657.70

*1587*  
*20% = 1269.6*

AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

CHEE AIK THUAN (HP. 96623655)  
ENG TECH, CAE MIMI / AM SAE-A  
MSAAA/Accident Damage Appraiser

# AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

601, Choa Chu Kang Street 62, # 04-07, Singapore 680601

E-mail Address: aasschee@singnet.com.sg

Tel: 96623655, 67655661

RCB No. 43037800M

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Registration No: **SKR 5792P**

Attachment to report no. TP/0049/12/2020

REPAIRER'S ESTIMATE		OUR RECOMMENDATIONS	
Replacement Of Damaged Panels/Parts and Labour Charges	S\$ Price	Conditions	S\$ Price
<b>REPLACEMENT OF DAMAGED PANELS/PARTS</b> Carried forward from page 1/5		<b>LUMP SUM REPAIR</b>  <b>LESS 20%</b>	
	6,756.70		5,657.70
12. 1 pc front steering rack and pinion <i>X Repair</i>	3,902.10	Bent - Allowable	3,902.10 <i>X</i>
		<b>NOTE:</b> Owner sent the vehicle to Kah Motor Co. Sdn. Bhd. (Agent for Honda Vehicle) for inspection while waiting for M/s Mova Automotive Pte. Ltd. to get the instruction from the 3rd party Insurance Co. (India International Insurance). It was the staff of Kah Motor Co. Sdn. who told him that the steering rack and pinion were also bent. That is why, from that time till today, 07 December 2020 ( more than one month) from the date of accident on the (04 November 2020), the owner did not replace the steering rack and pinion.)	
	-----		-----
	10,658.80		9,559.80
			1,911.96
			-----
			7,647.84
13. 4 pcs tyre @ 180.00 <i>X SVC</i> S.Nett	720.00	Owner went to replace all 4 tyres - Allowable 2 pcs only (Depreciation of 50%)	180.00 <i>X</i>
		<b>NOTE:</b> Owner went to replace all 4 tyres because he need to use the vehicle while waiting for M/S Mova Automotive Pte. Ltd. to get the instruction from the 3rd party Insurance Co. (India International Insurance), else vehicle will be left in the workshop over a month.	
	-----		-----
	11,378.80		7,827.84
	-----		-----

AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

**CHEE AIK THUAN** (HP. 96623655)  
 ENG TECH, CAE MIMI / AM SAE-A  
 MSAAA/Accident Damage Appraiser

# AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

601, Choa Chu Kang Street 62, # 04-07, Singapore 680601

E-mail Address: aasschee@singnet.com.sg

Tel: 96623655, 67655661

RCB No. 43037800M

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Registration No: SKR 5792P

Attachment to report no. TP/0049/12/2020

REPAIRER'S ESTIMATE		OUR RECOMMENDATIONS	
Replacement Of Damaged Panels/Parts and Labour Charges	S\$ Price	Conditions	S\$ Price
<b>LABOUR CHARGES</b>			
01. Labour charges - R & R fender glass	120.00	Not Necessary Reason being: 01. Fender to be repaired (refer to item no. 03)	0.00
02. Labour charges - R & R seat, garnish and etc.	100.00	Necessary Reason being: 01. To remove and refit trim garnishes, trim finishers and etc. to facilitate the repairing of the rear LH fender.	<del>80.00</del> X
03. Labour charges - Panel beating	1,000.00	Necessary Reason being: 01. To remove damaged parts and attachments, repair and reshape dented panels, renew damaged panels and parts (refer to our recommendations), align and refit attachments.	<del>750.00</del> 400
04. Labour charges - R & R rear bumper reverse sensor.	80.00	Necessary Reason being: 01. To transfer rear bumper reverse sensors (4 pcs) onto new rear bumper.	<del>80.00</del> 40
05. Labour charges - R & R front LH door and LH sliding door attachments.	100.00	Necessary Reason being: 01. To transfer/renew front LH door and LH sliding door attachments to new doors.	100.00 /
	1,400.00		1,010.00

AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

CHEE AIK THUAN (HP. 96623655)  
ENG TECH, CAE MIMI / AM SAE-A  
MSAAA/Accident Damage Appraiser



# AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

Qualified Automobile Accident Damage Appraisers/Loss Adjusters  
601, Choa Chu Kang Street 62, # 04-07, Singapore 680601

E-mail Address: aasschee@singnet.com.sg

Tel: 96623655, 67655661

RCB No. 43037800M

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Registration No: **SKR 5792P**

Attachment to report no. TP/0049/12/2020

REPAIRER'S ESTIMATE		OUR RECOMMENDATIONS	
Replacement Of Damaged Panels/Parts and Labour Charges	S\$ Price	Conditions	S\$ Price
<b>LABOUR CHARGES</b>			
Carried forward from page 3/5	1,400.00		1,010.00
06. Labour charges - Spray painting	1,400.00	Necessary Reason being: 01. To respray paint on rear bumper, rear LH fender, LH sliding door, front LH door, door wingmirror, front LH fender and other affected areas.	<del>1,300.00</del> 1200
07. Labour charges - Anti rust proofing	150.00	Necessary Reason being: 01. To apply/respray anti rust proofing.	<del>100.00</del> X
08. Labour charges - R & R steering rack.	300.00	Necessary Reason being: 01. To remove and renew steering rack and pinion.	150.00 ✓
09. Labour charges - Wheel alignment.	100.00	Necessary Reason being: 01. To conduct and adjust wheel alignment.	<del>100.00</del> 60
08. Labour charges - Lighting system	30.00	Necessary Reason being: 01. To check wiring, lighting system and conduct water leak test.	<del>30.00</del> X
09. Labour charges - Reset system	400.00	Necessary Reason being: 01. To erase and reset system.	<del>350.00</del> X
	3,780.00		1950
			3,040.00

AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

CHEE AIK THUAN (HP. 96623655)  
ENG TECH, CAE MIMI / AM SAE-A  
MSAAA/Accident Damage Appraiser

# AUTOMOTIVE APPRAISER AND SURVEYING SERVICES

Qualified Automobile Accident Damage Appraisers/Loss Adjusters  
601, Choa Chu Kang Street 62, # 04-07, Singapore 680601  
E-mail Address: aasschee@singnet.com.sg  
Tel: 96623655, 67655661  
RCB No. 43037800M

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Registration No: **SKR 5792P**

Attachment to report no. TP/0049/12/2020

REPAIRER'S ESTIMATE		OUR RECOMMENDATIONS	
Replacement Of Damaged Panels/Parts and Labour Charges	S\$ Price	Conditions	S\$ Price
CARRIED FORWARD FROM PAGE 2/5			
Replacement of damaged panels/part	11,378.80	3219.6	7,827.84
CARRIED FORWARD FROM PAGE 4/5			
Labour Charges	3,780.00	20% 2550	3,040.00
	-----		-----
	15,158.80	5 Days.	10,867.84
	-----		-----
			LUMP SUM
			8,700.00

### NOTE:

Please refer to our recommendations of S\$ 10,867.84.

In our opinion, the vehicle can be repaired at a Lump Sum of S'pore Dollars: **Eight Thousand And Seven Hundred Only.**

( S\$ 10,867.84 x 20% (S\$ 2,173.57) = S\$ 8,694.27)

### LUMP SUM CONTRACT

In view of the fact that the repairer has been offered a reduced budget to complete the repair. **(TOTAL REVISED LESS ANOTHER 20%),** the repairer should be entitled to exercise some discretion to complete the repair.

- To replace with New Parts (Genuine or Non Genuine Parts)
- To replace with Second Hand Parts (Imported or local Used Parts)
- To repair

The repairer would repair the vehicle to the entire satisfaction of the owner and in 'road worthy' condition.

The above terms and condition for the **LUMP SUM REPAIR CONTRACT** (Accident-Damaged Vehicle) is in line with the circular through a referendum from the Singapore Automobile Appraisers Association dated 25 May 2004.

Please find enclosed

- Letter from the Singapore Automobile Appraisers Association dated 25 May 2004
- Letter from The General Insurance Association Of Singapore dated 28 June 2004.
- Letter from the General Insurance Association Of Singapore dated 08 September 2005
- The New Paper reply from NTUC Income dated 19 September 2003.

**AUTOMOTIVE APPRAISER AND SURVEYING SERVICES**

CHEE AIK THUAN (HP. 96623655)  
ENG TECH, CAE MIMI / AM SAE-A  
MSAAA/Accident Damage Appraiser