

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI21000337/KTD3E2

**Date:** 22/02/2021

### REFERENCE

Insured/Claimant:	LIMELITE PRODUCTIONS PTE LTD	Policy No:	DMCVSNA00009892001		
Date of Loss:	01/01/2021	Nature of Claim:	OD	Claim No:	SNM21D200043/C01/THAMYL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF7372A	Engine No:	4P10C47737
Make & Model:	mitsubishi canter, 3.0 D FEA01BR2SDEB (M)	Chassis No:	FEA01BA20479
Reg. Date:	24/02/2017 (Man. Year: 2016)	Odometer:	224033 km
Colour:	Multi-colour		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	S\$48,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15 (D)
Front Left Side:	Kenda 6 mm	Rear Left Side:	Yokohama 8/8 mm
Front Right Side:	Kenda 6 mm	Rear Right Side:	Yokohama 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>- Excess (S\$)</b>	0.00	3,500.00	-3,500.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>-3,500.00</b>	<b>3,500.00</b>	

### INSPECTION

Date of Assignment:	08/01/2021	
Date Inspected:	08/01/2021	Inspected At: 38 WOODLANDS INDUSTRIAL PARK E1 #05-04/05
Estimated Period of Repair:	0.0 days	Repairer : Cheng Hoe Motor Pte Ltd

**Adjuster:** KENNETH KONG

**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

**TOTAL LOSS ASPECT**

Market Value :	\$48,000.00
OMV :	\$30,506.00
PARF Rebate (1) :	\$0.00
Quota Premium Paid :	\$48,901.00
COE Rebate (2) :	\$29,995.00
Total Rebate (1) + (2) = :	\$29,995.00

The total amount incurred will be Market Value \$48,000.00 minus Total Rebate \$29,995.00 = \$18,005.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

# REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Feb 2021)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEA01BR2SDEB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF7372A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >