

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 05 Apr 2021

## **Preliminary Advice**

|                    |                                                                                                                    |                         |              |
|--------------------|--------------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SKV8729H                                                                                                         |                         |              |
| TP Vehicle No      | : SGQ8383U                                                                                                         | Accident Date           | : 07/01/2021 |
| Make               | : TOYOTA PRIUS HYBRID                                                                                              | Assignment Date         | : 08/01/2021 |
| Date of Inspection | : 08/01/2021                                                                                                       | Est. Duration of Repair | : 10         |
| Inspection At      | : XIN YUN AUTO PTE LTD (KAKI BUKIT) (HQ)<br>8 KAKI BUKIT AVENUE 4, #05-23 PREMIER @ KAKI BUKIT<br>SINGAPORE 415875 |                         |              |

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 31,047.10 |
| Revised Amount              | :S\$ | 13,287.62 |
| Check Items (Estimated)     | :S\$ | 0.00      |
| Total                       | :S\$ | 13,287.62 |
| Lump Sum Repair             | :S\$ | 10,600.00 |

### **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

### **Remarks**

- ( ) The vehicle is economical for repair
- ( ) The vehicle is not economical for repair
- ( ) Part-by-Part repair
- ( ) Lump Sum repair
  
- ( X ) The above survey was conducted on a 'without prejudice' basis.