

XINYA AUTO SERVICES PTE LTD

Add: BLK 1002, BUKIT MERAH LANE 3 #01-75, Singapore 159719 Tel: 6270 3481 Fax: 6278 7522
E-mail: xinyaauto@singnet.com.sg

Date : 06-Jan-21

Address : KEITH LIM

BLK 153 MEI LING STREET
08-18
SINGAPORE 140153

Reference : TP 1269/01/21
Vehicle No : SKJ 9338J
Make/Model : HONDA ACCORD
Insurance Co. : NTUC

RE: QUOTATION REPAIRS TO SKJ 9338J FOR THIRD PARTY CLAIMS.

PARTS REQUIRED

QTY AMT \$

1)	REAR BUMPER <i>de</i>	1	\$ 709.15
2)	REAR BUMPER RETAINER <i>neu</i>	2	\$ 48.30
3)	REAR BUMPER BRACKET <i>neu</i> <i>7.81</i>	2	\$ 35.60
4)	REAR BUMPER ENFORCEMENT	1	\$ 245.60
5)	REAR BUMPER CLIPS <i>neu</i>	10	\$ 42.00
6)	BOOT COVER <i>h</i>	1	\$ 878.10
7)	BOOT COVER LOCK <i>neu</i>	1	\$ 110.95
8)	BOOT COVER HINGES <i>7 X su</i>	2	\$ 184.90 X
9)	BOOT COVER SPRING <i>7 X su</i>	2	\$ 110.40 X
10)	BOOT COVER WEATHER STRIPE <i>neu</i>	1	\$ 85.25
11)	BOOT COVER UNDER COVER <i>7 X su</i>	1	\$ 228.10 X
12)	BOOT COVER LAMPS <i>ca</i>	2	\$ 527.80
13)	BOOT COVER "H" EMBLEM <i>neu</i>	1	\$ 32.10
14)	BOOT COVER "ACCORD" EMBLEM <i>X an</i>	1	\$ 29.25 X
15)	BOOT COVER KEY LOCK <i>7 X su</i>	1	\$ 180.00 X
16)	BOOT COVER LOCK STRICKER <i>7 X su</i>	1	\$ 60.00 X
17)	TAIL LAMP <i>ca</i>	2	\$ 673.50
18)	END PANEL <i>7.81</i>	1	\$ 387.80
19)	END PANEL GARNISH <i>7.81</i>	1	\$ 97.75
20)	BOOT UNDER COVER BOARD <i>7 X su</i>	1	\$ 132.80 X
21)	EXHAUST SILENCER <i>X su</i>	1	\$ 1,241.30 X
22)	EXHAUST INSULATOR <i>X an</i>	1	\$ 85.40 X
23)	SPARE TYRE PANEL <i>X Repair</i>	1	\$ 386.20 X
24)	SPARE TYRE COVER <i>X su</i>	1	\$ 233.05 X
25)	NOS PLATE LIGHT <i>7 X su</i>	1	\$ 57.00 X
26)	NOS PLATE LIGHT GARNISH <i>chk</i>	1	\$ 132.80

4806.70
2076
3205.36

LIST PRICE TOTAL
LESS DISCOUNT 20%
LIST PRICE TOTAL AFTER LESS

\$ 6,935.10
\$ 1,387.02
\$ 5,548.08

27)	REVERSE SENSOR <i>neu</i>	4	\$ 440.00 250
28)	NOS PLATE W/CASING <i>X su</i>	1	\$ 50.00 X
29)	REVERSE CAMERA <i>7 X su</i>	1	\$ 180.00 X
30)	BOOT COVER TOP SPOILER (ASSC) <i>X su</i>	1	\$ 220.00 X

NETT PRICE TOTAL

\$ 890.00

TOTAL PARTS COST

\$ 6,438.08

LABOUR AND MISCELLANEOUS CHARGES

- 1) TO REMOVE & REPLACE REAR BUMPER, BOOT COVER ENFORCEMENT AND TO PANEL BEAT FENDER CUT & END PANEL, SPARE TYRE PANEL. 1050
- 2) TO PUTTY & SPRAY PAINT REAR BUMPER, BOOT COVER (INNER & OUTER) END PANEL, SPARE TYRE PANEL, REAR BOTH FENDER & OTHER AFFECTED AREA. 1200
- 3) TO REMOVE & REFIT ALL SEATS, ROOF BOARD & OTHER ACCESSORIES UPHOLSTRY TO ALLOW HOT WORKS. 800.00 / 100
- 4) TO REMOVE & REPLACE REAR EXHAUST SILENCER 120.00 X 100
- 5) TO CHECK & RECTIFY WIRING & FIT REVERSE SENSOR AND REVERSE CAMERA. 240.00 / 100
- 6) TUFF KOTE 300.00 / 100

LABOUR TOTAL

TOTAL ESTIMATED REPAIR COST

\$ 11,898.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair
Hp 90010068

7 days

HS

08/01/2021

@1410

Repair after

repair

3205.36

250.00

2550.00

6005.36

20%

4804.28

4s - 4,800

7 days