



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CENTRAL NARCOTICS BUREAU (MHA09)

Ref: CC2/CNB21000349/R1eq2

CORPORATE SERVICES DIVISION
BLK B
POLICE CANTONMENT COMPLEX
393 NEW BRIDGE ROAD
SINGAPORE 088763

Date: 26/03/2021

Code: CNB

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 998T	Veh. Inspected	SLP 2395X
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	11/01/2021

2. Vehicle Particulars & Condition

Make & Model	HONDA JAZZ 1.3 CVT	c.c	1318
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JHMGK3850HX200288	Colour	WHITE
Odometer	53667 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65 R15	DUNLOP	5 mm
L/H Front Tyre	175/65 R15	DUNLOP	5 mm
R/H Rear Tyre	175/65 R15	DUNLOP	5 mm
L/H Rear Tyre	175/65 R15	DUNLOP	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/12/2020	Inspection Date	11/01/2021
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 2395X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	PANEL ,R.FR.FENDER (SN)	BENT	306.67	306.67
1	PANEL COMPR.FR.DOOR (SN)	TO REPAIR SEE LABOUR	594.30	-
1	DISKALUMINIUM WHEEL 16X6J (SN)	SERVICEABLE	643.27	-
			1,644.24	356.67
	<u>LABOUR</u>			
	REMOVE & TRANSFER ITEMS TO NEW FR R DR ADJUST .	NOT NECESSARY	800.00	-
	RESET VEHICLE SMART ENTRY SYSTEM.		800.00	560.00
	REMOVE & RENEW FR R FENDER RENEW ALL DAMAGE PARTS.INCLUSIVE OF THE REPAIR OF PANEL COMPR.FR.DOOR .		2,500.00	975.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		1,500.00	1,040.00
	WHEEL ALIGNMENT X4 .	NOT NECESSARY	180.00	-
			5,780.00	2,575.00
GRAND TOTAL			7,424.24	2,931.67
RECOMMENDED COST OF REPAIRS				2,931.67

Report Ref No. CC2/CNB21000349/R1eq2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLP 2395X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLP 2395X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

