SS. REC. BY: CAME CC2 C	NB 21000349 RIE / forc
	ASSICNMENT
om: Date:	Ven No: SLP 2395X Yr Regn: 2017 1 MAY
limated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
O / TP / WS / TP RES / OD RES / EVA / INV / MIV	Truck / Trailer or
Inspect Vehicle No: SLP 2395 X	Make: HONDA JA22 1.3 CVT., . C.C 1318
Workshop m/s KAH MOTUR	Colour WHITE A/C: Insured/Std/NI/NA
258 MERGARI RO.	Sp.Reading US36(7 T/Radio: Insured / Std / NI / NA
sured: CNB	Eng/No:
olicy No.	C/NO: JHMGK 3850HX 200288 .
aims No.	Gen. Cond: Good / Fair / Poor / Burnt
ım İnsured: Excess:	Steering: Inorder/ Jainmed / Leaked / Burnt or
(Client's Record)	Brake: (norder / Jammed / Leaked / Burnt or
ake of Veh:	Modi: Nil / Strim / STD AVRim or
	Tyre Size: F: 175/65R15
(Policy Condition)	R: 2 4
Remark: The veh had commenced its N/S	
repair at the time of inspection.	TOYO/YOKO or
sal. or Market Value: 52 K	Front Rear
DAC Accident Rport: Consistent?: Yes or No	R/Bal, 5 mm R/Bal, 5 mm
GIA / PR Seen: Consistent?: Yes or No	
Est. Repairs: days Res.: Yes or No	
Lum Sum: % · 3 Val.: Yes or No	
Wild Communication Communicati	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS	ole: IN/OUT 0/S FRE
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	
Repair (mit-tok	
•	
. :	
Di Tira Tira Tira Tira Tira Tira Tira Tir	
Dale Mine, File Pass to? : Prell. Report	Days Of Repair:
: Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2)	Add Fee: Site Insp (\$) s+Rs_si
	:Interview (\$) Photos
Reput Formal:	:Tech, Invs (\$) Others
Lump Sun / LE.A: (\$)	:Weelland (%
	TOTAL
	e Maria V
	to the control of



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Customer

Registration No

Chassis No

Model

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Document No.

: SQT20004262

Page

P O BOX 1313

ROBINSON ROAD SINGAPORE 902613

: JHMGK3850HX200288

: JAZZ 1.3LXR CVT 17YM

: SINGAPORE POLICE FORCE

Customer No. Svc Advisor

: 29. Dec 2020 : WS054

Date

: JACK NG

Engine No

: L13B11020203

Date | Time

: 29. Dec 2020 8:29:36 AM

Amount

Surveyor Name

Unit Price Disc %

Survey Date

Authorisation Date

Owner's Name : LEW SHAUN MARC Ins Policy No.

Date of Accident

: 28/12/2020

: SLP2395X

0% GST Amount **Amount** incld GST

QUOTATION

Company Ref. No.: S60FC1380G

GST Reg No.: M200050223

Description TP DIRECT SETTLEMENT (J/NO:) OWNER:LEW SHAUN MARC OWNER INSURER: AXA INSURANCE ACC DATE:28/12/2020

> SURVEYED BY: DATE:

REF NO: TP INSURER: TP VEH: QX 998 T

PANEL, R.FR.FENDER 5 60211-T5R-A00ZZ PANEL COMPR.FR.DOOR (4) 67010-T5A-U00ZZ DISKALUMINIUM WHEEL 16X6J XXL 42700-T5A-N91

SUNDRIES

408.90 792.40 857.70

1

25 25

25

Sum Item

594.30 643.27

100.00

800.00

800.00

2500.00

1500.00

180.00

306.67

41.60 635.90 45.03 688.30 1544.24 108.10 1,652.34

7.00

56.00

56.00

175.00

105.00

399.00

21.47

328.14

107.00

856.00

856 00

2675.00

1605.00

6,099.00

192.60

192.60

REMOVE & TRANSFER ITEMS TO NEW FR R DR. BKDR12R **ADJUST** BC012R RESET VEHICLE SMART ENTRY SYSTEM REMOVE & RENEW FR R FENDER. RENEW ALL BKFE12R DAMAGE PARTS @650 X1.5 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. 1 BP02R 9520 42

BO-WHEEL ALIGN X4 WHEEL ALIGNMENT X4

1500.00 1040/ Sum Labor

180.00

100.00 50

800.00 560 XM

800.00 560/

2500.00 975

5700.00

180.00 12.60

12.60

Survey By

BOSUN

Date & Time

Total Amount

Sum Ext. Service

7,424.24

519.70 7,943.94

Printed on 11/1/2021 8:38:23 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Customer

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

: SINGAPORE POLICE FORCE Document No.

P O BOX 1313 **ROBINSON ROAD**

SINGAPORE 902613

Registration No : SLP2395X

Chassis No : JHMGK3850HX200288 Model : JAZZ 1.3LXR CVT 17YM

Owner's Name

: LEW SHAUN MARC

Ins Policy No.

Date of Accident : 28/12/2020

Item Description

Excess

Status

Signature

4 days Resent Le fore paint

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

· No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 11/1/2021 8:38:23 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

QUOTATION

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

Page 2

: SQT20004262 : 29. Dec 2020

: WS054

Customer No. : JACK NG

Svc Advisor **Engine No** : L13B11020203

Date | Time : 29. Dec 2020 8:29:36 AM

Unit Price Disc %

Total (Inclusive of GST)

Surveyor Name

Date

Survey Date

Authorisation Date

0% GST

Amount

incld GST

Amount

Amount

7,943.94