



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWERSINGAPORE 048623

Ref: CS3/SMO21000351/Uvd3e2

Date: 14/01/2021

Code: SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBH 1401D	Veh. Inspected	SKT 6901A
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2100076/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	08/01/2021

2. Vehicle Particulars & Condition


Make & Model	HONDA JAZZ (A)	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JHMGK5850FX202883	Colour	YELLOW
Odometer	105362 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/50 R16	FALKEN	6 mm
L/H Front Tyre	195/50 R16	FALKEN	6 mm
R/H Rear Tyre	195/50 R16	FALKEN	6 mm
L/H Rear Tyre	195/50 R16	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.



5. General Information

Accident Date	07/01/2021	Inspect Date / Time	08/01/2021 (01:48 PM)
Survey held at	CARSMITH PTE LTD BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**

Report Ref No. CS3/SMO21000351/Uvd3e2

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.